

### **How to Calibrate the Moisture Meter?**

1. Keep the power button pressed in the OFF state, remove any one battery from the back compartment and replace it.
2. Release the power button, then the meter enters calibration mode with "--" displayed on the screen.
3. Make sure there is no obstruction within 10cm. Press ▲ and ▼ button in turn, then the - - symbol blinks. Turn off the meter 5s later.
4. Power on the meter. You can start measurement once the screen displays 0.0% sturdily.