


User Manual

Digital Kitchen Scale

Model No.:EK6015



Question or Concerns? support@etekcity.com
visit etekcity.com for more products

Thank you for purchasing the EK6015 Digital Kitchen Scale by Etekcity®. Ideal for both industrial and personal use, this scale is designed with the capability to calculate weight in four units of measurement. The scale features simple auto-zero and tare functions for quick measurement convenience. Simplicity starts here.

IMPORTANT: Please read and comply with all the instructions and warnings provided in this manual before using the product. Failure to comply with the instructions and warnings provided herein may result in inaccurate results and/or damage to the product.

Important Safety Information

- Always place the scale on a hard, dry and flat surface before measurement in order to ensure measurement accuracy.
- **DO NOT** exceed the 5,000g weight capacity. An overload indicator will appear on the LCD display if the limit is exceeded.
- **DO NOT** immerse the scale in water or corrosive liquids. If liquid is spilled on the scale platform, immediately wipe the scale clean with a soft cloth in order to avoid potential damage to the scale.
- If the scale is stained with any food ingredients, clean immediately to avoid potential staining.
- When replacing batteries, make sure to insert them under the correct polarity as indicated within the battery compartment.
- Replace the batteries if the lowbattery indicator is displayed in order to ensure the highest accuracy.
- **DO NOT** mix new and used batteries to power the device.
- This scale is not intended for commercial or heavy-duty use.

- Handle the scale with care. Keep the scale in a cool, dry environment.
- To clean, wipe the surface with a damp soft cloth.
- If the scale fails to turn on, check whether the batteries are installed correctly. Replace the batteries if necessary.
- If the scale is not in use for an extended period of time, take out the batteries to extend the scale service lifetime.

Features

- High precision sensor
- Backlit LCD display
- Zero / Tare function
- Auto off after 10 seconds of inactivity
- Low battery indicator
- Overload indicator
- Quick unit conversion

Specifications

- Weight Capacity: 5,000g (176 oz)
- Division Value: 1g
- Units:g/ml/oz/lb'oz
- Batteries: 2 x AAA 1.5 V DC
- Dimensions: 180mm x 140mm x 18mm

Set-Up

The included AAA batteries are preinstalled in the scale. Open the battery compartment cover located on the backside of the scale and remove the plastic strip from the battery compartment to allow the batteries to power the device. Reapply the battery compartment cover.

Battery Replacement

1. Open the battery compartment cover on the backside of the scale.
2. Take out the used batteries and dispose them properly.
3. Install new AAA 1.5 V batteries, taking note of the correct polarity displayed in the battery compartment.
4. Reseal the battery compartment.

Operation

1. Place the scale on a flat and level hard surface for measurement.
2. Press the 'ON/OFF' button to turn on the scale. Wait until the screen display zero before measuring.
3. Place the object of measurement on the center of the weighing platform.
4. Allow the scale to adjust to the weight of the object for a few seconds before it displays the final measured reading on the LCD screen.

Zero / Tare Function

The tare function allows the user to deduct the weight of a container from the total weight in order to determine the net weight of the contents excluding the weight of the container which holds them.


1. Turn on the scale and wait for the screen to display zero. If the screen does not display zero automatically, press the 'Z/T' button to auto-adjust to zero.
2. Place the desired object which is to be excluded, on the center of the measuring platform.
3. Press the 'Z/T' button to tare the current weight of the object. The screen should now display zero.

4. Place the desired item(s) to be weighed on the center of the measuring platform or within the tared container to calculate the net weight of the desired item(s).

Unit Conversion: To change the unit of measurement, press the 'UNIT' button until the LCD display indicates the desired unit of measurement.

Automatic Power Off: For battery power conservation, the scale will automatically power off after 10 seconds of inactivity.

Manual Power Off: Press and hold the 'ON/OFF' button for 2 seconds to manually turn off the digital scale at any time.

Error Message	Reason	Solution
"EEEE"	Scale overload. Maximum weight capacity: 5,000g (176 oz).	Take the object off the scale to avoid damage.
	Battery power is low.	Install new batteries.

Package Contents

- 1 x Etekcity® Digital Kitchen Scale
- 1 x User Manual
- 2 x AAA 1.5 V DC batteries