

**EUROGUIDE - MAKE MODEL YEAR GUIDELINES**

The Euroguide is a document to help identify the right products needed for TPMS maintenance. There are three different coverage lists : a "Make\Model\Year Look up", a "Sensor Look Up" and a "Service Kits Look Up".

**Make\Model\Year Look up:** This list helps identify the right sensors needed using a Make/Model/Year classification.

1/ Choose the car manufacturer and the model of the car in the column " **Make Model**".

2/ Identify the code of the car in the second column " **Model code**".

3/ The columns " **Start of Application**" and " **End of Application**" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.

4/ If the car falls within this time range, all the necessary information in the following columns can be found (same line, from left to the right)

5/ **Schrader Part Number:** This is the new After Market reference to order the matching sensor for the car.

6/ **OE Sensor reference:** This is car manufacturer's part number for the sensor.

7/ **Sensor Description :** This is the name and description of the sensor matching with the selected car.

8/ **Direct TPMS car park in Market:** number of vehicles introduced in the reference market with direct TPMS systems using the specific sensor indicated in the OE sensor reference column.

Notice: VDO and HUF are protected brands of the companies VDO and HUF. Schrader is a distributor of VDO and HUF products. Product design, description and brands are properties of HUF and VDO.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk.

This list will be regularly updated.

For further information: [tpmseuroshop.com](http://tpmseuroshop.com) or [aftermarket@schradler.co.uk](mailto:aftermarket@schradler.co.uk)

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
<b>Alfa Romeo</b>							
159	939	2005-7	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	314
4C	4C	2013-6	2021-03	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,154
8C Competizione	920	2007-1	EOP	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	85
Brera	946	2005-11	2010-12	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	31
Giulia	UT	2014-4	EOP	4016	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	6,517
Giulia (LCV)	UT	2014-4	EOP	4016	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	1
MiTo	955	2013-8	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	270
MiTo	955	2008-6	2013-07	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	992
MiTo (LCV)	955	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	7
Spider	946	2006-6	2010-12	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	31
Spider	J12A	2015-4	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	714
<b>Alpina</b>							
Alpina 3	E90	2007-3	2009-09	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	95
Alpina 3	E90	2009-9	2012-12	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	26
Alpina 3	F30	2013-1	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	535
Alpina 3	F32	2013-4	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	471
Alpina 4	F32	2014-3	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	126
Alpina 5	F10	2014-3	2017-10	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	78
Alpina 5	F10	2010-1	2014-02	4010	36 10 6 790 054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	142
Alpina 6	E63	2006-3	2010-12	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	3
Alpina 6	F06	2014-3	2018-10	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	14
Alpina 6	F12	2010-12	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	21
Alpina 6	F12	2015-1	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	4
Alpina 7	F01	2014-3	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	8
Alpina 7	F01	2010-9	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	13
XD3	F25	2014-3	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	155
XD3	F25	2010-9	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	8
<b>Aston Martin</b>							
Cygnat	630L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Rapide	VH400	2010-1	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	319
V12 Zagato	Zagato	2012-9	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1
V8 Vantage	AM305	2005-7	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	702
V8 Vantage	VH600	2014-1	2021-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	131
Vanquish	AM310	2012-6	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	403
Virage	AM803	2011-5	2017-08	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
<b>Audi</b>							
A3 Sportback	AU370	2012-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	30,462
A3 Sportback (LCV)	AU370	2012-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
A4	AU461/AU471	2004-11	2007-10	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,986
A4	AU481	2015-1	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	91,270
A4	AU491	2014-10	2021-10	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,911
A4 (LCV)	AU481	2014-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	25
A4 Allroad	AU486	2009-3	2015-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,524
A4 Cabrio	AU465/AU475	2006-1	2008-07	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597
A5	AU484	2006-12	2015-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,679
A5 Cabrio	AU485	2008-11	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,669
A5 Sportback	AU483	2009-7	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,213
A5 Sportback (LCV)	AU483	2014-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A6	AU561	2009-6	2011-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597
A6	AU561	2004-5	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597
A6	AU571	2011-1	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	44,838
A6 (LCV)	AU571	2011-1	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4
A6 Allroad	AU566	2009-6	2011-08	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	171
A6 Allroad	AU566	2006-5	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	161
A6 Allroad	AU566	2000-4	2005-08	4001	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	93
A6 Allroad	AU572/4	2012-1	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,924
A7	AU573	2010-9	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,343
A8	AU631	1999-9	2010-07	4001	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	8,960
A8	AU641	2009-11	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	8,863
Q3	AU316	2011-7	2018-03	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	24,277
Q3 (LCV)	AU316	2011-7	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
Q5	AU416	2008-9	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,022
Q5 (LCV)	AU416	2008-9	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Q7	AU716	2014-6	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,504
Q7	AU716	2006-3	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,986
Q7	AU716	2009-6	2014-05	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,695
Q7	AU726	2014-6	2021-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,687
Q7 (LCV)	AU726	2014-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
R8	AU714	2015-4	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	534
R8	AU714	2009-6	2015-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,100
R8	AU714	2007-4	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597
R8	AU724	2015-4	2023-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	204
TT	AU334	2014-2	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,084
<b>Bentley</b>							
Azure	BY824	2006-6	2011-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5
Azure	BY835	2013-10	2020-10	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	130
Continental	ROLLS ROYCE	2014-3	EOP	4009	4F0 907 275 B	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	1
Continental Flying Spur	BY611	2005-3	2010-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15
Continental Flying Spur	BY621	2010-1	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,592
Continental GT	BY624	2014-3	EOP	4009	4F0 907 275 B	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	1,351
Continental GTC	BY615	2006-12	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,443
Continental GTC	BY625	2011-11	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,621
E-CUV	BY716	2014-11	2022-10	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	369
Mulsanne	BY831	2009-9	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,596
<b>BMW</b>							
1-Series	F20	2011-7	2019-12	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	180,720
1-Series	E88/E82	2009-9	2011-07	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	630
1-Series (LCV)	F20	2014-6	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	49
2-Series	F22	2013-11	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	48,652
2-Series Active Tourer	F45	2014-7	2021-06	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	47,629
2-Series Gran Tourer	F46	2015-1	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	17,469
3-Series	E46	1997-5	2004-12	4002	36 11 2 360 420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	2,966
3-Series	E90	2014-3	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	298
3-Series	F30	2011-11	2019-12	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	218,912
3-Series	E90/E91/E92/E93	2009-9	2012-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	63
3-Series	E90/E91/E92/E93	2006-6	2009-09	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	63

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
3-Series (LCV)	F30	2014-5	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	6
3-Series GT	F34	2013-3	2020-01	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	34,331
4-Series	F32	2013-10	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	82,255
4-Series Gran Coupe	F36	2014-7	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	30,305
5-Series	F10	2014-3	2016-10	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	109,786
5-Series	F10	2010-9	EOP	4010	36 10 6 790 054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	33,861
5-Series	E39	1998-9	2003-07	4002	36 11 8 378 682	Beru-Huf Clamp-in Separate valve G1 433MHz BMW	1,780
5-Series	E60/E61/F07	2006-3	2010-08	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,260
5-Series GT	F07	2014-3	2017-03	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,397
5-Series GT	F07	2010-9	2014-02	4010	36 10 6 790 054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	534
6-Series	E63	2006-3	2010-12	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	593
6-Series	F12	2014-3	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	3,613
6-Series	F12	2011-3	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	358
6-Series Gran Coupe	F06	2011-3	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	314
7-Series	F01	2014-6	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	6,551
7-Series	G11	2015-7	2022-06	3057	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	1,364
7-Series	E39	1998-9	2001-10	4002	36 11 2 360 420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,890
7-Series	E65	2001-11	2003-11	4002	36 11 2 360 420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,890
7-Series	E65/E66	2006-3	2008-07	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,890
7-Series	F01/F02/E68	2008-9	2010-08	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,890
C-MPV	F46	2015-7	2022-03	3057	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	15,197
i3	I01	2013-8	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	20,963
i8	I12	2014-1	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	3,209
X1	E84	2014-3	2015-06	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	46,181
X1	E84	2009-9	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	4,451
X1	F48	2015-7	2021-12	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	9,048
X1 (LCV)	E84	2014-3	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	3
X3	F25	2010-11	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	5,597
X3	F25	2014-3	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	54,649
X3	E83	2003-3	2010-08	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	630
X3 (LCV)	F25	2014-6	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	14
X4	F26	2014-4	2020-03	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	32,024
X5	E70	2006-10	2010-09	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	4,450
X5	E70	2010-3	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	9,929
X5	F15	2013-5	2020-03	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	84,785
X5	E53	1999-10	2004-04	4003	36 14 6 752 128	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz BMW	1,890
X5 (LCV)	F15	2014-6	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	18
X6	E71	2007-12	2011-10	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	593
X6	F16	2014-8	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	17,438
X6	F16	2015-8	2021-07	3057	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	7,267
X6 (LCV)	F16	2015-10	EOP	3057	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	1
Z4	E89	2014-3	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	4,862
Z4	E89	2010-9	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	522
Z4	E89	2009-5	2010-08	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	30
Z4 Coupe	E86	2006-4	2008-08	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	63
<b>Bugatti</b>							
Veyron	BG824	2005-9	2011-11	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3
<b>Buick</b>							
Park Avenue	G-CAR	1997-1	2004-06	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	32
<b>Cadillac</b>							
ATS	A1BL	2014-7	EOP	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	226
ATS	A1SL	2012-7	2018-03	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	413
CTS	A1LL	2013-9	EOP	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	392
CTS	GMX206	2008-1	EOP	3049	20922901	Schrader Snap-in GEN4 type 433MHz GM	87
CTS	GMX226	2010-6	EOP	3049	20922901	Schrader Snap-in GEN4 type 433MHz GM	175
CTS	GMX322	2006-1	2007-06	3055	25774007	Schrader Clamp-in Gen J 433MHz GM	371
Escalade	GMT926	2005-12	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,338
Escalade	GMT926	2014-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	160
Escalade	K2UL	2014-1	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	660
Escalade (LCV)	GMT926	2005-12	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	8
SRX	GMT166	2009-7	EOP	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	3,216

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
SRX	GMT265	2005-6	2009-02	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	36
STS	GMX295	2005-6	2011-04	3053	25758221	Schrader Clamp-in Gen J 433MHz GM	9
XLR	GMX215	2003-5	2009-04	3053	25758221	Schrader Clamp-in Gen J 433MHz GM	8
XTS	P1LL	2012-5	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	4
<b>Chevrolet</b>							
Aveo	G1SC	2010-11	2016-12	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	16,025
Aveo	T250	2014-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
Aveo	G1JC	2014-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,490
Camaro	GMX521	2010-11	EOP	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	390
Captiva	C100	2006-6	2014-05	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	7,766
Captiva	C100	2006-6	EOP	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	2,296
Cobalt	G1LC	2013-2	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	23,701
Colorado	GMi700	2014-6	EOP	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	453
Colorado (LCV)	GMT355	2003-10	EOP	3053	25758221	Schrader Clamp-in Gen J 433MHz GM	63
Corvette	GMX245	2010-2	2014-12	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	847
Corvette	GMX245	2004-7	2010-01	3053	25758221	Schrader Clamp-in Gen J 433MHz GM	1,507
Cruze	D1JC	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	816
Cruze	D1WC	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,444
Express	GMT610	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	73
Express (PC)	GMT610	2002-7	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	2
Malibu	V300	2014-7	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	38
Malibu	V300	2011-7	2014-06	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	16
Malibu	V300	2010-7	2011-06	3049	20922901	Schrader Snap-in GEN4 type 433MHz GM	2,561
Matiz	M100	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	12,805
Matiz	M200	2014-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	43
Niva	2123	2014-6	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	27,283
Orlando	J309	2010-9	2017-12	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	20,322
Orlando	D1NC	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	4,620
Orlando (LCV)	D1NC	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	3
Silverado	K2XC	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	16
Spark	M1JC	2009-7	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	4,130
Suburban	GMT931	2006-3	2008-07	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	4
Tracker	G1UC	2014-1	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	6,421
Trailblazer (LCV)	GMT360	2001-1	EOP	3055	25774007	Schrader Clamp-in Gen J 433MHz GM	3
Trax	G1UC	2012-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	9,173
Volt	D1JCI	2010-11	EOP	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,155
Volt	D2JCI	2015-6	2020-09	3071	13594222	Schrader Snap-in Faraday 433MHz GM	133
<b>Chrysler</b>							
200	UF	2015-2	EOP	4016	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	92
300	LE48	2014-6	EOP	3008	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3
300	LX	2011-1	2016-06	3008	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	210
300/300C	LE48	2005-6	2010-06	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	6,300
300C	LX	2014-6	EOP	3008	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	42
Delta	844	2013-2	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	8
Grand Voyager	RT	2011-1	2017-09	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	1,672
Grand Voyager	RT	2007-7	2011-01	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1,670
Sebring	JS41C	2006-8	EOP	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	49
Sebring Convertible	JS27	2007-2	EOP	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	42
Town & Country	RT	2007-7	2011-01	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	630
Voyager	RT	2014-6	EOP	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3,046
<b>Citroen</b>							
Berlingo	B9	2013-10	2017-01	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	23,236
Berlingo (LCV)	B9	2008-1	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	4,914
Berlingo Multispace	B9	2013-10	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	11,677
C4	B5	2004-11	2008-06	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,978
C4	B7	2010-6	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	43,470
C4 Aircross	J4	2014-4	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	8,906
C4 Aircross (LCV)	J4	2014-4	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	15
C4 Picasso	B58	2006-5	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	135,427
C5	X3/X40	2004-8	2007-12	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	93,511
C5	X40	2000-12	2004-07	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	71,474

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
C5	X7	2013-9	2016-09	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	24,299
C5	X7	2008-1	2013-09	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	70,666
C5 (LCV)	X7	2007-10	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	33
C6	X6	2005-9	2012-12	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,489
C8	V3	2014-7	EOP	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	15
C8	V3	2005-9	2014-06	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	328
C8	V3	2002-2	2005-10	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	11,912
C-Elysee	M3/M4	2012-10	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	22,524
C-ZERO	S4	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	991
C-ZERO (LCV)	S4	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	10
DS4	B75	2010-12	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	20,506
DS4	B75	2014-2	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	28,283
DS4 (LCV)	B75	2010-12	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	46
DS5	B81	2014-2	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	23,540
DS5	B81	2011-6	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	12,902
DS5 (LCV)	B81	2011-6	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	10
Jumper	X2/50	2013-12	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	10,628
Jumper	X2/50	2006-1	2013-11	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	7,734
Jumper Chassis	X2/50	2014-6	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	94
Jumper Combi	X2/50	2014-6	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	2,165
Jumpy	G9	2014-6	EOP	3001	9677130580	Schrader Snap-in GEN4 type 433MHz PSA HP	21,402
Jumpy Combi	G9	2014-6	EOP	3001	9677130580	Schrader Snap-in GEN4 type 433MHz PSA HP	5,165
Nemo	225	2007-10	2015-12	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	14,987
Nemo Multispace	225	2007-10	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	3,619
<b>Dacia</b>							
Dokker	K67	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	30,997
Dokker Van	F67	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	22,641
Duster	H79	2010-2	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	261,294
Duster Pickup	U79	2015-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	9
Duster Pro	H79	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,443
Lodgy	J92	2012-1	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	47,412
Lodgy (LCV)	J92	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3
Logan	L52	2012-11	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	70,081
Logan MCV	K52	2013-4	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	51,182
Logan Van	F90	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3
Sandero	B52	2012-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	233,269
Sandero Pro	B52	2012-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	65
<b>Daewoo</b>							
Gentra	J200	2013-8	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	28,787
Nexia	T-CAR	2014-6	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	48,228
Nexia	T	2014-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	12,791
<b>Dodge</b>							
Avenger	JS41D	2006-11	EOP	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	95
Caliber	PM49	2006-1	EOP	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	270
Caravan	RT	2011-6	2017-05	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	7
Challenger	LC22	2010-2	2017-09	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	150
Challenger	LC22	2008-1	2010-01	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	59
Charger	LD	2010-12	2014-09	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3
Charger	LD	2014-10	2016-06	3007	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	1
Durango	WD75	2010-11	EOP	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	295
Journey	JC49	2015-10	EOP	3066	Info not available	Schrader Snap-in Faraday 433MHz Chrysler	10
Journey	JC49	2014-7	2015-09	3007	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	29
Journey	JC49	2011-1	2014-06	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	291
Nitro	KA	2006-8	EOP	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	186
Nitro (LCV)	KA	2006-8	2012-06	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	9
Ram	DS	2010-1	2012-12	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	4,546
Viper	ZD	2013-8	2015-06	3008	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3
Viper	ZD	2015-7	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	3
<b>Ferrari</b>							
550 Maranello	F133	2002-3	EOP	4001	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	315
612 Scaglietti	F137	2004-4	2011-06	4001	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	315

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
California	F149	2014-11	EOP	4009	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	442
California	F149	2008-7	2014-10	4009	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	3,087
Enzo	F152	2003-9	2004-12	4005	193867	Beru-Huf Clamp-in Separate valve G1 plus 433MHz Ferrari	96
F12	F152	2012-10	EOP	4009	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,256
F430	F131	2007-7	2009-12	4009	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	30
F430	F131	2005-5	2007-06	4001	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	31
F430 Scuderia	F131	2007-7	2012-06	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	63
F458	F142	2009-12	EOP	4009	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	7,716
F599 GTB	F141	2004-3	EOP	4001	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	65
FF	F151	2011-6	EOP	4009	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	928
LaFerrari	F150	2013-7	EOP	4009	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	164
<b>Fiat</b>							
500	312	2015-8	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	51,524
500	312	2007-5	2015-07	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	133,724
500 (LCV)	312	2007-5	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	31
500C	312	2007-5	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	43,505
500L (LCV)	330	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2
Bravo	198	2007-1	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	134
Doblo	223	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1
Doblo	263	2009-12	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	87,626
Doblo Combi	263	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	964
Ducato	X2/50	2014-6	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	8,201
Ducato	SEVEL X2	2014-6	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	346
Ducato Chassis	X2/50	2014-6	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2
Ducato Combi	X2/50	2014-6	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,629
Fiorino	225	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	3,591
Fiorino Qubo	225	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	971
Freemont	JF	2015-10	EOP	3066	Info not available	Schrader Snap-in Faraday 433MHz Chrysler	3,753
Freemont	JF	2014-7	2015-09	3007	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	11,254
Freemont	JF	2011-3	2014-06	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	38,714
Freemont (LCV)	JF	2011-3	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	25
Idea	350	2003-9	2012-07	3017	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	320
Linea	200	2007-3	2016-03	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	42,372
Linea	200(2)	2015-11	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1
Punto	199	2005-9	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	70,871
Qubo	225	2007-10	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2,333
Scudo	G9	2013-11	2015-12	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	15,810
Scudo	G9	2006-9	2013-10	3001	9677130580	Schrader Snap-in GEN4 type 433MHz PSA HP	14,943
Scudo Chassis	G9	2014-3	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	23
Scudo Combi	G9	2013-11	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	4,323
Scudo Combi	G9	2006-9	2013-10	3001	9677130580	Schrader Snap-in GEN4 type 433MHz PSA HP	3,854
Sedici	YY2	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	581
Strada	178	1998-9	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2,047
Ulysse	V1	2001-1	2010-10	4031	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	796
Ulysse	V1	2002-2	2005-10	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	1,598
<b>Ford</b>							
B-Max	B232	2014-6	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	63,321
B-Max (LCV)	B232	2014-6	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	32
C-MAX	C344	2014-3	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	123,799
C-Max (LCV)	C344	2010-8	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	199
Econoline	VN127	2006-1	EOP	3018	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	17
Ecospport	B515	2014-10	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	32,154
Ecospport	B515	2012-7	2014-09	3019	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,552
Edge	CD539	2014-8	EOP	3023	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	4,950
Edge	U387	2014-6	EOP	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	315
Edge	CD389	2015-1	EOP	3023	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	5,158
Escape	C520	2012-4	2017-06	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	5
Escape	U377	2009-1	2012-04	3018	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	3
Expedition	U222(2)	2005-1	2008-11	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	63
Explorer	U502	2010-11	EOP	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,687
F-150	P415	2008-9	2014-06	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	63
Fiesta	B299	2014-5	2015-12	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	385,324

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Fiesta Van	B299	2014-6	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	12,996
Focus	C346	2014-3	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	369,729
Focus (LCV)	C346	2010-12	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	190
F-Series	P415	2008-9	EOP	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	52
Galaxy	CD340	2015-1	EOP	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	6,261
Galaxy	CD340	2006-1	2014-12	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	5,276
Galaxy	CD390	2015-1	2022-06	3023	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	18,194
Galaxy (LCV)	CD390	2014-11	EOP	3023	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	29
Kuga	C394	2014-6	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	11
Kuga	C520	2012-11	2019-09	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	147,647
Kuga (LCV)	C520	2012-11	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	36
Mondeo	CD345	2007-1	2015-03	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	1,260
Mondeo	CD391	2014-10	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	114,476
Mondeo (LCV)	CD391	2013-9	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	13
Mustang	S197	2014-5	EOP	3024	DR3V-1A180-BA	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	63
Mustang	S197	2004-9	2014-04	3024	DR3V-1A180-BA	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	117
Mustang	S550	2014-5	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	3,354
Mustang (Import)	S197	2004-9	2014-04	3018	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	1
Ranger	P375	2014-6	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	22,299
S-MAX	CD340	2006-2	EOP	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	5,747
S-MAX	CD539	2015-1	2021-06	3023	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	37,697
S-MAX	CD389	2015-1	EOP	3023	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	35,982
S-Max (LCV)	CD340	2006-2	EOP	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	21
S-Max (LCV)	CD539	2014-10	EOP	3023	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	75
Tourneo Connect	V408	2014-3	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	15,327
Tourneo Courier	B460	2014-10	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	11,077
Tourneo Courier	B460	2014-3	2014-09	3019	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	231
Tourneo Custom	V362	2013-4	EOP	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	3,427
Transit	V347	2014-6	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	88
Transit	V348	2014-6	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	19
Transit	V363	2013-6	EOP	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	131,510
Transit Chassis	V348	2014-3	EOP	3019	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	87
Transit Chassis	V363	2013-6	EOP	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
Transit Combi	V348,V363	2013-6	2021-03	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	3
Transit Combi	V363	2013-6	EOP	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,859
Transit Connect	V408	2014-3	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	81,291
Transit Courier	B460	2014-10	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	36,306
Transit Courier	B460	2014-3	2014-09	3019	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1,238
Transit Custom	V362	2013-4	EOP	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	20,021
<b>GMC</b>							
Sierra	K2XG	2013-4	2019-06	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	23
Yukon	GMT922	2005-12	2013-12	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	244
Yukon	GMT922	2014-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	18
Yukon	K2UG	2014-3	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
<b>Honda</b>							
Accord	QE	2013-7	EOP	4072	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	2,070
Accord	2GB	2013-7	EOP	4072	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	9,638
Accord CrossTour	2NX	2014-6	EOP	4072	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	616
Jazz	2AP,2HQ	2014-6	EOP	4064	Info not available	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	1,489
Jazz	2WF	2014-9	EOP	4064	Info not available	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	29,463
Jazz	2AP	2014-3	EOP	4064	Info not available	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	27,942
<b>Hummer</b>							
H2	H2	2002-4	2008-12	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	189
H3	GMT345	2005-3	2012-01	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	95
H3 (LCV)	GMT345	2005-3	2012-01	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	95
<b>Hyundai</b>							
Accent	MC	2014-6	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	2
Accent	RB	2014-3	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	16,993
B-CUV	GC	2015-4	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	7,851
Elantra	HD	2014-3	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10
Elantra	MD	2014-3	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	11,859

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Equus	VI	2014-3	EOP	4052	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	860
Genesis	BH	2014-6	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	12
Genesis	DH	2014-1	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	2,201
Genesis Coupe	BK	2014-3	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	446
Grandeur	HG	2014-3	EOP	4061	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	337
i10	PA	2014-3	EOP	4026	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	541
i10	IA	2013-11	EOP	3059	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	164,730
i10	IA,PA	2007-10	EOP	4026	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	5
i10 (LCV)	PA	2014-3	EOP	4026	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	5
i20	PB	2014-7	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	4,653
i20	PB	2008-8	2014-06	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	12,454
i20	GB	2014-1	EOP	3060	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	123,727
i20	GB,IB	2014-11	EOP	3060	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	89,699
i20 (LCV)	IB	2015-1	EOP	3060	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	34
i20 (LCV)	GB	2014-11	EOP	3060	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	17
i30	FD	2007-10	EOP	4026	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	2,436
i30	GD	2011-11	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	133,152
i30 (LCV)	GD	2011-10	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	11
i40	VF	2014-4	EOP	4078	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	35,028
i40	VF	2011-4	2014-03	4061	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	3,229
i40 (LCV)	VF	2011-4	2014-03	4061	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	4
ix20	JC	2013-5	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	50,001
ix20	JC	2010-9	2013-09	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	49,866
ix20 (LCV)	JC	2010-9	2013-09	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	11
iX35	LM	2014-3	EOP	4062	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	90,934
iX35	TL	2015-10	EOP	4060	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	6,743
iX35 (LCV)	LM	2014-3	EOP	4062	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	18
iX35 (LCV)	TL	2015-10	EOP	4060	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	1
Santa Fe	CM	2005-12	EOP	4057	52933-2B000	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	11
Santa Fe	DM	2012-4	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	28,571
Santa Fe (LCV)	DM	2014-3	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	17
Solaris	RB	2014-3	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	156,020
Sub-Compact SUV	IB	2015-5	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	19,487
Veloster	FS	2011-2	EOP	3056	52933-2V100	Schrader Snap-in GENA type 433MHz HKMC	2,951
<b>Infiniti</b>							
EX	P53B	2007-10	2016-03	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	95
FX	P53C	2014-9	2020-09	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	693
FX	P53C	2008-3	2014-08	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,550
G	L53A	2013-4	2019-01	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	7
G	L53A	2006-8	2013-03	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	931
M	L53E	2009-12	EOP	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	100
Q50	L53H	2014-3	EOP	4071	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	4,649
Q50	D53H	2013-4	EOP	4071	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	5,019
Q70	L53E	2013-11	EOP	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	825
QX50	P53B	2014-6	EOP	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,367
QX50	P53B(2)	2015-11	EOP	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	29
QX70	P53C	2014-6	EOP	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	4,259
<b>Jaguar</b>							
F-Type	X152	2012-10	EOP	4019	C2D21599	Conti Clamp-in TG1C 433MHz Ford	10,061
RD-7	X760	2015-4	EOP	4066	Unknown	Conti Clamp-in TG1C 433MHz JLR	16,975
XE	X760	2015-1	EOP	4066	Unknown	Conti Clamp-in TG1C 433MHz JLR	21,566
XF	X250	2007-11	EOP	4023	C2C41655	Conti Clamp-in TG1B 433MHz JLR	36,240
XF	X260	2015-9	EOP	4066	Unknown	Conti Clamp-in TG1C 433MHz JLR	1,860
XJ	X351	2014-6	EOP	4019	C2D21599	Conti Clamp-in TG1C 433MHz Ford	3,335
XJ	X350	2003-5	2009-09	4023	C2C41655	Conti Clamp-in TG1B 433MHz Ford	1,796
XK	X150	2006-1	2014-07	4023	C2C41655	Conti Clamp-in TG1B 433MHz Ford	2,739
X-Type	X400	2007-1	EOP	4023	C2C41655	Conti Clamp-in TG1B 433MHz Ford	1,197
<b>Jeep</b>							
B-CUV	520	2014-10	EOP	4016	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	29,600
Cherokee	KK	2007-7	EOP	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	498
Cherokee	KL	2014-3	EOP	4068	68239720AB	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	15,341

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Cherokee (LCV)	KL	2014-6	EOP	4068	68239720AB	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	7
Compass	MK49	2014-9	EOP	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3,643
Compass	MK49	2006-5	2014-08	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	19,079
Grand Cherokee	WK74	2010-7	EOP	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	59,643
Grand Cherokee	WH	2005-3	2010-06	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	5,032
Grand Cherokee (LCV)	WK74	2010-5	EOP	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	47
Patriot	MK74	2006-12	2014-08	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	122
Patriot	MK74	2014-9	EOP	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	17
Patriot (LCV)	MK74	2006-12	EOP	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	31
Renegade	520	2014-3	EOP	4016	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	38,155
Wrangler	JK72	2010-10	2013-12	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	28,820
Wrangler	JK72	2014-1	EOP	3007	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	4,805
Wrangler	JK72	2006-8	2010-09	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,520
Wrangler (LCV)	JK72	2006-8	EOP	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3,079
<b>Kia</b>							
Cadenza	VG	2013-10	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	107
Carens	RP	2012-12	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	5,282
Ceed	ED	2014-3	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	18
Ceed	JD	2012-3	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	136,376
Ceed (LCV)	JD	2014-3	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	10
Cerato	YD	2013-3	EOP	4063	52933-A7100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	21,250
Magentis	TF	2014-3	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	2
New Carens	RP	2013-6	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	85
Optima	TF	2013-8	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	5,575
Optima	TF	2011-9	2013-08	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	7,365
Picanto	TA	2014-4	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	91,389
Picanto (LCV)	TA	2014-6	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	32
Quoris	KH	2013-1	EOP	4052	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	760
Rio	JB	2014-6	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	12
Rio	UB	2012-11	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	79,396
Rio	QB	2000-1	EOP	4056	52933-3J000	Lear Clamp-in Variable Angle ver 1 433MHz HKMC	144,083
Rio (LCV)	UB	2000-1	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	44
Rio (LCV)	QB	2014-3	EOP	4052	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	13
Sorento	UM	2012-7	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	5,367
Sorento	XM	2009-5	2012-09	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	10,759
Sorento (LCV)	UM	2012-7	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	27
Sorento (LCV)	XM	2014-3	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	20
Soul	PS	2013-11	EOP	3059	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	28,806
Soul (LCV)	PS	2013-10	EOP	3059	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	11
Sportage	SL	2010-1	EOP	4062	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	162,295
Sportage (LCV)	SL	2014-3	EOP	4062	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	26
Venga	YN	2014-4	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	28,188
Venga (LCV)	YN	2010-2	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	16
<b>Lamborghini</b>							
Aventador	LB834	2011-5	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	726
Aventador	LB734	2014-3	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	326
Gallardo	LB714	2010-2	2013-05	4009	4F0 907 275 D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	877
Gallardo	LB714	2007-6	2010-01	4009	4F0 907 275 D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	605
Gallardo	LB724	2013-6	2021-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	774
Huracan	LB724	2014-3	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	436
Huracan	LB624	2014-3	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	470
Murcielago	LB824	2010-11	EOP	4009	4F0 907 275 D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	6
<b>Lancia</b>							
Delta	844	2008-4	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	835
Delta	PK	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	5,246
Delta (LCV)	844	2014-3	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	2
Flavia	JS27	2010-10	EOP	4015	68078768AA	Conti Clamp-in TG1C 433MHz Chrysler	47
Flavia	UF	2014-2	EOP	4016	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	413
Musa	848	2004-7	EOP	3017	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	355
Thema	LX	2011-1	EOP	4031	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	4,697
Voyager	RT	2007-7	2011-01	3006	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,901

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Voyager	RT,RU	2011-1	2015-10	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	571
Voyager (LCV)	RT	2011-1	EOP	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	186
<b>Land Rover</b>							
Defender	L316	2014-6	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	12,701
Defender (LCV)	L316	2014-6	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	2,881
Discovery	L319	2009-9	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	4,525
Discovery (LCV)	L319	2009-9	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	63
Discovery (LCV)	L319	2004-7	2009-09	4023	LR031712	Conti Clamp-in TG1B 433MHz Ford	103
Discovery Sport	L550	2014-1	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	43,538
Freelander	L359	2014-3	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	1,293
Freelander	L550	2006-10	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	7,377
Freelander (LCV)	L550	2006-10	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	39
Range Rover	L322	2005-1	2009-12	4023	LR031712	Conti Clamp-in TG1B 433MHz Ford	1
Range Rover	L405	2010-1	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	4,839
Range Rover (LCV)	L322	2005-1	2009-12	4023	LR031712	Conti Clamp-in TG1B 433MHz Ford	21
Range Rover (LCV)	L322	2002-3	2003-02	4003	YDB 0000 60	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Land Rover	32
Range Rover (LCV)	L405	2014-6	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	38
Range Rover (LCV)	L405	2010-1	2022-04	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	19
Range Rover Evoque	L538	2014-3	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	83,955
Range Rover Evoque	L538	2012-1	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	77,888
Range Rover Evoque (LCV)	L538	2011-7	2018-09	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	124
Range Rover Sport	L494	2014-3	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	39,992
<b>Lexus</b>							
C-CUV	600A	2014-11	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	14,709
CT	080A	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	14,178
ES	980L	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3,958
GS	920L	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,484
GX	837L	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,296
IS	030L	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,022
IS	400A	2013-7	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	19,942
IS	720A	2015-2	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	684
LF-A	973L	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
LS	250L	2014-1	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,070
LX	220L	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,974
NX	600A	2014-3	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	17,567
RC	720A	2014-1	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,155
RX	640L	2014-6	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	8,769
RX	740A	2015-4	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	67
<b>Lotus</b>							
Elise	Monza	2008-1	EOP	3058	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	788
Evora	Eagle	2010-1	EOP	3058	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	454
Exige	Monza	2008-1	EOP	3058	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	569
<b>Mahindra</b>							
B-CUV	S101	2015-9	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	4
Bolero	CL/MM	2014-6	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	6
Bolero	U301	2015-7	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	5
NC	CL/MM	2014-6	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	3
Scorpio	MI	2014-6	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	130
Scorpio	W105	2014-6	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	51
Thar	CL/MM	2014-6	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	13
XUV500	W201	2014-6	EOP	3062	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	50
<b>Maserati</b>							
Ghibli	M157	2013-11	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	8,788
GranCabrio	M147	2015-7	2021-03	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	125
GranCabrio	M147	2009-9	2015-06	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	211
GranTurismo	M145	2014-1	2020-03	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	852
GT Coupe	M145	2009-7	2013-12	4009	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	443
GT Coupe	M145	2002-1	2009-06	4001	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	158
GT Coupe	M138	2014-3	EOP	3009	95518233/670002790	Schrader Clamp-in Gen Gamma 433MHz Maserati / Alfa Romeo	9
Levante	WM	2015-4	2021-09	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,214
Quattroporte	M139	2010-1	EOP	4009	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	630

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Quattroporte	M139	2004-4	2009-12	4001	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	637
Quattroporte	M156	2013-1	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,203
<b>Maybach</b>							
57/62	W240	2002-9	EOP	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	53
<b>Mazda</b>							
2	J03	2014-5	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	52,985
2	J64F	2007-12	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	15,925
2	J03W	2014-1	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	57,971
2 (LCV)	J03	2014-5	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	7
3	J68C	2009-6	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	1,058
5	J74G	2010-7	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	10,126
6	J61A	2007-8	2012-08	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	352
6	J71E	2013-3	2018-09	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	47,501
6 (LCV)	J71E	2014-6	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	11
B-Series	J26E	2015-6	EOP	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	50
BT-50	J26E	2011-5	EOP	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	228
CX-5	J53C	2011-11	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	101,961
CX-5 (LCV)	J53C	2011-11	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	19
CX-7	J31H	2009-6	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	158
CX-9	J50C	2010-8	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	527
MX-5	J04C	2014-3	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	5,642
MX-5	J04C	2010-3	2014-02	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	3,368
MX-5	J12A	2015-10	EOP	4028	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	564
<b>McLaren</b>							
MP4-12C	P11	2011-4	EOP	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	546
P1	P12	2013-1	EOP	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	28
<b>Mercedes-Benz</b>							
A-Class	W176	2013-1	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,245
A-Class	W176	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	116,334
A-Class (LCV)	W176	2014-6	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	91
B-Class	W246	2013-1	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	111,773
B-Class (LCV)	W246	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	44
C-Class	C204	2014-3	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	10,847
C-Class	C205	2015-1	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	1,845
C-Class	W204	2013-1	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	18,036
C-Class	W205	2014-1	2021-03	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	261,284
C-Class (LCV)	W205	2014-7	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	10
C-Class Coupe	C204	2012-12	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	8,732
C-Class Coupe	C205	2015-6	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	17,917
Citan	VS10	2012-9	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	24,527
Citan Combi	VS10	2014-1	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,144
CL	C216	2006-7	2014-03	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	115
CL	C217	2014-4	2020-06	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,089
CL	C215	1999-7	2005-09	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	177
CLA	C117	2012-12	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	290
CLA	C117	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	57,202
CLS	C218	2013-1	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,707
CLS	C218	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,655
CLS	C218	2009-8	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,039
CLS	C219	2004-10	2005-06	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	295
CLS	C219	2005-1	2009-07	4040	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	354
E-Class	C207	2014-6	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	33,302
E-Class	W212	2013-1	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	41,169
E-Class	W212	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	79,247
E-Class	W212	2009-1	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	9,800
E-Class Coupe	C207	2009-1	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,268
GLA	X156	2014-1	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	41,118
GLA	X156	2014-12	2020-12	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	60,843
GLC	X253	2015-1	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	12,756
GL-Class	X164	2009-6	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,015
GL-Class	X164	2006-9	2009-07	4040	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	59

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
GL-Class	X166	2013-1	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,700
GL-Class (LCV)	X166	2014-3	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	2
GLE Coupe	C292	2015-1	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,369
GLK	X204	2012-12	2015-09	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	22,650
GLK	X204	2015-10	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	3,440
GLK	X253	2015-10	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	3,143
GLK (LCV)	X204	2014-6	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	47
GLK (LCV)	X253	2015-10	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	1
GT	C190	2014-1	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	2,765
G-Wagen	G463/461	2013-1	2022-12	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,830
G-Wagen	G463/461	2007-4	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,754
G-Wagen (LCV)	G463/461	2012-12	2022-12	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	17
MLC	C292	2012-12	2019-03	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,072
ML-Class	W166	2014-7	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	27,013
ML-Class	W166	2011-7	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,276
ML-Class (LCV)	W166	2014-6	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	39
R-Class	V251	2013-1	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	277
R-Class	V251	2005-6	2009-07	4040	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	443
R-Class	V251	2009-7	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,352
S-Class	W221	2005-10	2009-06	4040	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	2,955
S-Class	W221	2013-1	2013-06	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	451
S-Class	W221	2009-7	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,371
S-Class	W222	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	17,414
S-Class	W220	1999-7	2005-09	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	886
S-Class Coupe	C217	2014-7	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,127
S-Class Pullman	X222	2014-3	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	502
SL	R230	2005-1	2009-07	4040	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	1,182
SL	R230	2001-1	2005-05	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	886
SL	R231	2014-6	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	2,577
SL	R231	2013-1	2014-05	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,221
SL	R231	2009-8	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,678
SLC	C190	2015-1	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	3,441
SLK	R172	2013-1	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	11,564
SLK	R172	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	8,193
SLR	C199	2004-1	2010-12	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	555
SLS	C197	2013-1	2023-09	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	35
SLS	C197	2010-2	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,535
Sprinter	NCV3	2014-6	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	113,102
Sprinter (LCV)	NCV3	2006-6	2011-10	4038	A 002 540 95 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	6,300
Sprinter Combi	NCV3	2013-1	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	8,956
V-Class	VS20	2014-3	EOP	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	18,258
V-Class	W638	2014-6	EOP	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	23
Viano	VS20	2014-6	EOP	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	124
Viano (LCV)	VS20	2014-8	2023-07	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	342
Viano (LCV) (Lo-Line)	W639	2003-7	2014-06	4038	A 002 540 95 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	3,150
Viano (LCV) (Mid-Line)	W639	2003-7	2014-06	4038	A 002 540 95 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	3,150
Vito	VS20	2014-7	EOP	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	51,140
Vito Combi	VS20	2012-12	2023-04	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	9,840
<b>Mini</b>							
Clubman	F54	2015-7	2022-06	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	3,656
Clubman	R55	2009-8	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	4,599
Clubman	R55	2007-8	2009-09	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	61
Clubman (LCV)	F54	2015-1	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	1
Clubman (LCV)	R55	2014-6	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	17
Clubvan	F54	2015-7	2022-05	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	255
Clubvan	R55	2012-7	2015-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	168
Countryman	R60	2014-7	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	54,019
Countryman	R60	2010-8	2014-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	75,874
Countryman (LCV)	R60	2014-7	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	7
Coupe	R58	2014-7	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	2,871
Coupe	R58	2011-7	2014-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	321
Mini	F56	2013-12	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	159,514

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Mini	R56	2014-6	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	21,993
Mini (LCV)	F56	2014-1	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	11
Paceman	R61	2012-11	2014-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,780
Paceman	R61	2014-7	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	7,046
Roadster	R59	2011-12	2014-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	490
Roadster	R59	2014-7	EOP	4069	36106798872	Beru-Huf Clamp-in 433MHz BMW	3,691
<b>Mitsubishi</b>							
ASX	ZC	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	50,399
ASX (LCV)	ZC	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11
Attrage	EL-L	2014-3	EOP	4079	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	440
i-MiEV	TQ	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,191
L200	CR	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11,549
L200	4P00	2014-11	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	17,776
L200	4P00.CR	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	2,087
Lancer	GS41	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11,358
Lancer	JT41	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	327
Outlander	RE	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	58,191
Outlander	GS45X.RE	2014-3	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	918
Outlander (LCV)	RE	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	7
Pajero	BK	2014-7	EOP	4079	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	9,363
Pajero (LCV)	BK	2014-7	EOP	4079	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	151
Pajero Sport	CR45	2014-6	EOP	4079	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	7,108
Spacestar	EL	2014-7	EOP	4079	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	28,341
<b>Nissan</b>							
370Z	C53D	2008-10	EOP	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,765
370Z	RC53D	2009-3	EOP	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	684
Almera	LB1A	2013-5	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	76,436
Altima	L42A	2014-3	EOP	4071	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1
Atleon	F91A	2014-6	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	181
Atleon	F91G	2014-1	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	1,646
Cabstar	F91A	2014-6	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	5,330
Cabstar E	F91A	2014-6	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	1,234
C-Hatch	B12L	2014-10	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	73,215
Frontier	H60A	2014-9	2023-03	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	48
GT-R	D52E	2007-9	2015-12	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,684
Juke	P12C	2015-10	EOP	4047	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	29,348
Juke	P12C	2010-5	2015-09	4047	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	136,498
Juke (LCV)	P12C	2010-5	EOP	4047	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	52
Leaf	B12G	2010-10	EOP	4047	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	20,328
Micra	B02A	2010-3	EOP	4077	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	73,194
Micra (LCV)	B02A	2010-3	EOP	4077	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	4
Murano	P42D	2007-10	EOP	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,870
Murano	P42M	2014-10	EOP	4071	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1,947
Murano (LCV)	P42M	2014-10	EOP	4071	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1
Navara	H60A	2014-9	2020-06	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	224
Navara	D22.H61B	2014-3	EOP	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,175
Note	J02C	2013-8	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	85,393
Note (LCV)	J02C	2012-3	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	33
NP300	H60A	2014-9	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	590
NV200	X11M	2014-4	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	16,123
NV200 Combi	X11M	2014-4	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	4,841
NV300	X82	2014-9	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	9,082
NV300 Combi	X82	2014-9	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	1,004
NV400	X62	2014-6	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	3,950
NV400 Combi	X62	2014-6	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	358
Primastar	X83	2014-6	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	320
Primer	ED	2001-12	2007-05	3037	40700 AV600	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Nissan	1,350
Pulsar	B12L	2014-3	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	61,501
Qashqai	P32S	2013-12	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	453,036
Qashqai (LCV)	P32S	2013-12	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	302
Sentra	L12F	2014-8	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	16,287
Teana	L42L	2014-1	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	13,368

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Terrano	H79N	2014-3	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	10,906
Tiida	B11C	2014-3	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	71
Tiida	B12L	2014-4	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	13,244
X-Trail	P32R	2013-11	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	78,200
X-Trail (LCV)	P32R	2013-11	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	108
<b>Opel</b>							
Adam	GM 4403	2014-8	2015-08	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	53,068
Adam	GM 4403	2015-8	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	19,000
Adam	GM 4403	2013-1	2014-07	3027	13581562	Schrader Snap-in GEN4 type 433MHz GM	407
Adam (LCV)	GM 4403	2014-3	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	2
Agila	H0310	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,301
Ampera	D1JOI	2011-9	EOP	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	776
Ampera	D2JCI	2015-1	EOP	3071	13594222	Schrader Snap-in Faraday 433MHz GM	14
Antara	C105	2010-11	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	630
Antara	C105	2006-8	2010-11	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	687
Astra	D2JO	2015-8	EOP	3071	13594222	Schrader Snap-in Faraday 433MHz GM	3,511
Astra	GM A3300	2004-1	2010-12	3031	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,865
Astra	GM P3400	2009-10	2011-09	3026	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	6,876
Astra	GM P3400	2014-6	EOP	3033	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	316,958
Astra	GM P3400	2011-9	2014-05	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	13,365
Astra (LCV)	D2JO	2015-1	EOP	3071	13594222	Schrader Snap-in Faraday 433MHz GM	1
Astra Van	D2JO	2015-1	EOP	3071	13594222	Schrader Snap-in Faraday 433MHz GM	1
Astra Van	D2JO, GM P3400	2014-6	EOP	3033	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	21
Astra Van	GM P3400	2014-6	EOP	3033	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	125
Cascada	D1AO	2014-6	EOP	3033	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	4,915
Cascada	D1AO	2013-1	2014-05	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,148
Combo	263	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	18,062
Combo Combi	263	2014-6	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2,487
Corsa	GM 4530	2014-11	2015-02	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	53,952
Corsa	GM 4530	2015-3	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	4,848
Corsa Van	GM S4400	2014-6	EOP	3027	13581562	Schrader Snap-in GEN4 type 433MHz GM	4,557
Corsa Van	GM 4530	2015-3	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	5,943
Insignia	GM G3700	2008-10	2011-09	3026	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	28,654
Insignia	GM G3700	2014-5	EOP	3033	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	69,563
Insignia	GM G3700	2011-9	2014-04	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	32,336
Karl	M2JO	2015-1	EOP	3063	13598773	Schrader Snap-in Faraday 433MHz GM	26,758
Meriva	GM S4470	2014-8	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	53,616
Meriva (LCV)	GM S4470	2014-6	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	61
Mokka	G1UO	2015-9	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	37,713
Mokka	G1UO	2012-6	2015-08	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	136,340
Mokka (LCV)	G1UO	2014-6	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	13
Movano	X62	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	14,711
Movano Combi	X62	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	490
Vectra	GM Z3200	2002-1	2008-09	3031	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	34,385
Vivaro	X82	2014-9	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	45,573
Vivaro	X83	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	180
Vivaro Combi	X82	2014-9	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,616
Vivaro Combi	X83	2014-3	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	54
Zafira	GM A3370	2011-7	2016-09	3031	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	8,384
Zafira	GM A3370	2009-1	2011-06	3031	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,865
Zafira (LCV)	GM A3370	2005-4	2008-12	3031	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	16
Zafira Tourer	GM P3470	2014-6	EOP	3033	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	42,821
Zafira Tourer	GM P3470	2011-9	2014-05	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	12,549
Zafira Tourer (LCV)	GM P3470	2011-9	EOP	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2
<b>Peugeot</b>							
1007	PF1	2005-1	EOP	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,260
1007	A08	2014-3	EOP	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1
107	590N	2014-7	EOP	4048	(blank)	Pacific Clamp-in Fixed Angle ver 1 433MHz PSA/Toyota	940
207	A7	2005-11	2013-09	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	4,245
207	A7	2013-9	2016-06	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	12,813
3008	T84	2008-11	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	178,923
3008	T84	2013-9	2016-09	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	159,406

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
3008 (LCV)	T84	2008-11	EOP	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	85
301	M3/M4	2012-10	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	16,694
307	T5	2003-11	2008-12	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	84,053
307	T5	2007-1	2007-12	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	119,224
308	T7	2013-9	2015-01	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	52,901
308	T7	2007-4	2013-08	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	131,494
4008	J3	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4,025
4008 (LCV)	J3	2014-6	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4
407	D2	2004-1	2006-02	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	238,449
408	T73	2014-6	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	9,140
5008	T87	2013-9	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	61,400
5008	T87	2009-9	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	95,827
5008 (LCV)	T87	2009-9	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	53
508	W2	2010-11	2013-09	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	86,651
508	W2	2013-9	2017-06	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	89,302
508 (LCV)	W2	2010-9	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	31
508 RXH	W24	2013-9	2017-12	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	717
508 RXH	W24	2012-1	EOP	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	18
607	Z8	2004-10	2009-03	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	10,134
607	Z8	1999-9	2004-10	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	14,903
807	V2	2004-10	2014-06	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	13,867
807	V2	2002-2	2004-09	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	12,518
Boxer	X2/50	2013-12	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	12,557
Boxer Combi	X2/50	2013-12	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	264
Expert	G9	2014-6	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	21,625
Expert Tepee	G9	2014-6	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	4,922
iOn	S3	2014-6	EOP	4029	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	914
iOn (LCV)	S3	2014-6	EOP	4029	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	21
Partner	B9	2014-6	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	75,025
Partner Tepee	B9	2014-6	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	26,497
Partner Van	B9	2014-6	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	3,919
RCZ	T75	2009-12	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	14,261
RCZ	T75	2013-10	2016-12	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	12,845
<b>Porsche</b>							
911	991	2011-12	2015-08	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	22,530
911	991	2015-9	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,460
911	997	2008-4	2011-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,587
911	997	2004-7	2008-03	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,720
918 Spyder	918	2013-9	2014-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
918 Spyder	918	2015-1	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	62
918 Spyder	PO815	2014-3	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	117
Boxster	981	2012-1	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	9,801
Boxster	987	2004-11	2008-10	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,433
Boxster	987	2008-11	2011-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,451
Carrera GT	980	2003-7	2006-04	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1
Cayenne	E2	2014-5	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,275
Cayenne	E2	2002-12	2006-12	4005	955 361 661 01	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Porsche	1,890
Cayenne	E2	2007-1	2010-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,865
Cayenne	E2	2010-6	2014-05	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	26,159
Cayenne (LCV)	E2	2010-3	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	10
Cayman	981	2013-3	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,645
Cayman	987	2005-1	2008-01	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	851
Cayman	987	2009-2	2013-02	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,515
Macan	PO416	2013-11	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	40,755
Panamera	970	2014-1	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,112
Panamera	970	2009-9	2013-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15,117
<b>Ram</b>							
1500	DS	2014-3	EOP	4068	68239720AB	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	241
<b>Renault</b>							
Captur	J87	2013-1	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	231,820
Captur (LCV)	J87	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	86

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
C-CUV	HFE	2014-10	EOP	4034	Info not available	Conti Snap-in TG1D 433MHz Renault	71,484
Clio	X85	2005-4	2014-05	3040	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	15,867
Clio	X98	2014-6	EOP	3073	40700 9987R	Schrader Snap-in Faraday 433MHz Renault T4	358,910
Clio Van	X85	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Clio Van	X98	2012-7	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,220
Clio Van	X10,X98	2014-3	EOP	3073	40700 9987R	Schrader Snap-in Faraday 433MHz Renault T4	124
Espace	J81	2002-7	EOP	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	55,787
Espace	JFC	2014-12	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	19,836
Espace (LCV)	J81	2002-7	EOP	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	5
Espace (LCV)	JFC	2014-7	EOP	4034	Info not available	Conti Snap-in TG1D 433MHz Renault	75
Fluence	L38	2009-10	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	37,400
Grand Espace	J81	2002-7	EOP	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	4,487
Kangoo	X61	2007-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	106,562
Kangoo	X61	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	68,140
Kangoo Passenger	X61	2007-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	31,420
Koleos	H45	2014-1	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	6,799
Koleos	H45	2008-2	2013-12	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	398
Laguna	LFD	2015-1	2021-09	4034	Info not available	Conti Snap-in TG1D 433MHz Renault	2,566
Laguna	X74	2000-12	2007-09	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	132,224
Laguna	X91	2007-10	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	47,848
Laguna (LCV)	X91	2007-6	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	32
Laguna Coupe	D91	2014-7	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	847
Laguna Coupe	D91	2008-7	2014-06	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,611
Latitude	L43	2010-9	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	2,781
Master	X62	2009-11	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	96,315
Master Passenger	X62	2009-11	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	2,977
Megane	B32	2009-11	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	288
Megane	B32,X95	2011-5	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	18,956
Megane	BFB	2015-1	EOP	4034	Info not available	Conti Snap-in TG1D 433MHz Renault	22,347
Megane	BFB	2015-4	2021-12	4034	Info not available	Conti Snap-in TG1D 433MHz Renault	16,939
Megane	X64	1997-1	2002-10	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	10,578
Megane	X84	2002-11	2008-11	4036	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	52,890
Megane	X95	2008-11	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	170,897
Megane Van	BFB	2015-1	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	263
Megane Van	X84	2014-3	EOP	4036	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	5
Megane Van	X95	2014-6	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	7,871
Modus	J77	2004-5	EOP	3040	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	2,644
Scenic	J95	2015-1	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	91,147
Scenic	J95	2009-1	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	146,726
Scenic	J95	2003-6	2007-10	4036	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	63,467
Scenic	J64	1997-1	2003-06	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	10,578
Scenic (LCV)	J95	2009-2	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	96
Symbol/Thalia	L35 (R)	2014-6	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Symbol/Thalia	L52	2013-4	2020-03	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	28,338
Trafic	X82	2014-3	2026-03	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	85,398
Trafic Passenger	X82	2014-3	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	12,692
Twingo	X07	2014-3	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	145,826
Twingo	X44	2007-1	2016-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	10
Twingo Van	X07	2014-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,984
Vel Satis	X73	2001-9	2009-11	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	130,486
Zoe	X10	2012-9	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	16,973
Zoe (LCV)	X10	2013-6	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	4
<b>Rolls-Royce</b>							
Ghost	RR04	2009-12	2010-08	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	367
Phantom	RR01	2007-9	2011-12	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	110
Phantom	RR01	2012-1	2016-09	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	69
Phantom Coupe	RR02	2014-6	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	30
Phantom Drophead Coupe	RR02	2006-8	EOP	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	110
Wrath	RR04	2014-3	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	604
<b>Saab</b>							
Saab 9-3	SB440	2014-6	EOP	3058	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	91

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
<b>Skoda</b>							
Citigo	SK120	2011-10	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,274
Fabia	SK250	2014-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,594
Fabia	SK260	2013-11	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,602
Fabia Van	SK250	2014-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	33
Fabia Van	SK260	2013-11	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	56
Octavia	SK371	2012-11	2019-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	31,442
Octavia (LCV)	SK371	2012-11	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Rapid	SK251/1	2012-9	2020-04	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,316
Rapid Spaceback	SK253/1	2013-10	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,840
Roomster (LCV)	SK258	2006-4	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11
Superb	SK481	2014-11	EOP	4067	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	31,681
Superb (LCV)	SK461	2008-3	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Yeti	SK316	2009-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,269
Yeti (LCV)	SK316	2009-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
<b>Smart</b>							
forfour	A453	2014-7	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	56,722
Fortwo	A452	2014-4	2021-03	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	89,549
Fortwo	C453	2014-3	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	78,636
Fortwo (LCV)	C453	2014-8	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	30
<b>Ssangyong</b>							
Actyon Sports	Q150	2014-3	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	534
Actyon SUT	Q150	2014-11	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	3
Actyon SUT	Q100	2014-3	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	86
C-CUV	X100	2015-5	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	3,245
Korando	C200/AS11	2013-8	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	42
Korando C	C200/AS11	2013-8	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1,327
Korando C (LCV)	C200/AS11	2013-8	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	5
Korando Sports	Q150	2014-11	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	815
Kyron	D100	2014-6	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	7,677
New Actyon	C200/AS11	2014-6	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	12,516
Nomad	Q150	2014-2	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	575
Rexton	Y200	2014-5	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	2,818
Rexton (LCV)	Y200	2014-5	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	43
Rexton SC	Y200	2014-5	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	14
Rodius	A100	2014-5	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1,997
Rodius (LCV)	A100	2014-5	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	4
Tivoli	X100	2015-1	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	4,525
<b>Subaru</b>							
BRZ	E88	2014-1	EOP	4045	28103-CA101	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	1,452
C-Concept	VL9	2014-6	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	13,817
Forester	FM5	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	24,141
Forester (LCV)	FM5	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	25
Impreza	MF1	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6,525
Impreza	ZR1	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	165
Impreza (LCV)	MF1	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	5
Justy	D71A	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1
Legacy	04AL	2014-10	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	10,384
Legacy (LCV)	04AL	2015-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2
Outback	04AL	2014-11	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,370
Outback	BF4	2014-9	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	5,506
Trezia	217A	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,196
Tribeca	00X	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	20
WRX	MF1	2014-3	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	401
WRX	VL9	2014-3	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,274
XV	MF1	2014-1	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	15,660
<b>Suzuki</b>							
Alto	YC5	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	16,410
Alto Van	YC5	2014-3	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1
Carry Van	YV7	2015-4	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	52
Celerio	YLA	2014-3	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	31,084

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Grand Vitara	YT4	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	12,545
Grand Vitara (LCV)	YT4	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	36
Jimny	YR7	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	8,848
Jimny	YR6,YR7	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,224
Jimny (LCV)	YR7	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	100
Kizashi	YW1	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	327
Splash	YV1	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	12,175
Splash	YV4	2013-9	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,803
Splash	YV5	2015-5	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	13,551
Splash	YV1,YV4	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	10
Swift	YP6	2014-4	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	21,764
Swift	YP6,YP7	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	55,348
Swift (LCV)	YP6	2014-6	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	15
SX4	YY1	2013-8	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	84
SX4	YY1,YY3	2013-8	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	149
SX4	YY3	2014-3	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	5
SX4 S-Cross	YAA	2013-11	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	96,496
SX4 S-Cross (LCV)	YAA	2013-11	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	74
Vitara	YFA	2015-1	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	35,024
<b>Tesla</b>							
Model S	Model S	2013-5	2014-08	4058	FS1511	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	16,519
Model X	Model X	2015-8	EOP	4058	FS1511	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	25
Roadster	DarkStar	2008-3	2010-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
<b>Toyota</b>							
Alphard	480L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	117
Alphard	580A	2015-5	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	109
Auris	130A	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	208,292
Auris	130L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Auris (LCV)	130A	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	32
Avalon	770N	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Avenis	312N	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Avenis	445L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	43,678
Avenis (LCV)	445L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Camry	050A	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,876
Camry	045L	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Corolla	079L,140N,340N	2013-8	EOP	4045	42607-42020	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	180
Corolla	140A	2014-1	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	408
Corolla	366A	2013-9	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	110,268
Corolla	150A	2014-10	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,928
Corolla	150L,252L	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	368
Corolla	466A	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	78,032
Dyna	U300-500	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Dyna	Dutro(2)	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	51
Dyna	U300-500,U600/C600	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12
Dyna	131N	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,496
FJ Cruiser	155L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
GT 86	E88	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,888
Hiace	550N	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	427
Highlander	440A	2014-10	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7,869
Highlander	397L	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Hilux	640A	2015-10	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,878
Hilux	669L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	20,829
IQ	630L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,402
Land Cruiser	215L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	14,012
Land Cruiser	611L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,999
Land Cruiser (LCV)	215L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	301
Land Cruiser Prado	611L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13,234
Land Cruiser V8	215L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	941
Previa	085X	2015-10	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13
Prius	590L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13,601
Prius	690A	2015-8	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	27
Prius (LCV)	590L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Prius (LCV)	690A	2015-9	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius Plus	030A	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7,627
Proace	G9	2014-6	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	6,962
Proace Combi	G9	2014-6	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	428
RAV4	410A	2013-1	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	22,970
RAV4 (LCV)	120L	2005-11	2012-12	4044	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	204
RAV4 (LCV)	410A	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	37
Sienna	580L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	124
Tundra	180L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	24
Tundra	480A/180L	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	43
Urban Cruiser	260L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	479
Venza	470L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,225
Verso	151L 595L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	458
Verso	595L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	33,256
Verso (LCV)	595L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	97
Verso-S	770L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,011
Verso-S (LCV)	770L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Yaris	020L	2014-3	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Yaris	850L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	247,690
Yaris (LCV)	850L	2014-6	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	381
<b>Volkswagen</b>							
Amarok	VN817	2009-11	2017-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,337
Caravelle	VN750	2003-12	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,070
CC	VW464	2014-6	EOP	4011	3AA 907 275 B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	1,204
Crafter	VN830	2006-4	2017-09	4038	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	16,081
Crafter Combi	VN830	2014-6	EOP	4038	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	402
Eos	VW465	2006-2	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	816
Golf	VW360	2014-5	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,923
Golf	VW370	2012-8	2018-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	211,922
Golf (LCV)	VW370	2012-8	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	83
Golf Plus	VW379	2014-2	2019-01	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	41,657
Golf Plus (LCV)	VW379	2014-2	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18
Golf Sportsvan	VW379	2014-3	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	20,423
Golf Sportsvan (LCV)	VW379	2014-4	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Golf SV	VW379	2014-3	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,256
Jetta	VW361	2010-7	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,479
New Beetle	VW314	2006-1	2010-07	4037	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	1,716
New Beetle	VW324	2011-8	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,518
New Beetle Convertible	VW325	2012-9	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,677
Passat	VW451	2005-3	2010-11	4037	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	20,027
Passat	VW471	2014-8	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,166
Passat	VW471	2010-8	2014-07	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	5,299
Passat	VW481	2014-7	EOP	4067	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	68,525
Passat (LCV)	VW481	2014-7	EOP	4067	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Passat CC	VW464	2014-9	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,995
Passat CC	VW464	2008-5	EOP	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	480
Phaeton	VW611	2002-4	2007-05	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	2,289
Phaeton	VW611	2010-6	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,086
Phaeton	VW611	2007-6	2010-05	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,399
Scirocco	VW364	2008-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,550
Scirocco (LCV)	VW364	2008-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Sharan	VW428	2010-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13,029
Sharan (LCV)	VW428	2010-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
Tiguan	VW316	2015-1	EOP	4011	3AA 907 275 B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	177,019
Tiguan	VW316	2011-5	EOP	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	2,808
Tiguan (LCV)	VW316	2007-8	EOP	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	18
Touareg	VW516	2002-10	2006-12	4005	7L0 907 275 B	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz VW/Porsche	3,433
Touareg	VW516	2007-1	2010-05	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,433
Touareg	VW526	2014-8	2017-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,787
Touareg	VW526	2010-1	2014-07	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,003
Touareg (LCV)	VW526	2010-3	2014-07	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5
Touran	VW378	2015-1	EOP	4067	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,256

Car Make	Car Model Code	Start of application	End of application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in market in 2015
Touran (LCV)	VW368	2010-7	EOP	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	38
Touran (LCV)	VW378	2015-1	EOP	4067	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	67
Transporter	VN750	2003-3	2017-03	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	30,692
Transporter	VN760	2015-9	EOP	3047	2N0907251	Schrader Snap-in Faraday 433MHz VW	12,026
Transporter Shuttle	VN750	2014-6	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	68
Transporter Shuttle	VN760	2015-9	EOP	3047	2N0907251	Schrader Snap-in Faraday 433MHz VW	23
Up!	VW120	2011-8	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	53,001
Up! (LCV)	VW120	2011-8	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
XL1	VW019	2013-8	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
<b>Volvo</b>							
C30	Y279	2006-9	2012-12	4021	31302096	Conti Clamp-in TG1C 433MHz Volvo	228
C70	Y281	2006-3	EOP	4021	31302096	Conti Clamp-in TG1C 433MHz Volvo	27
S40	Y276	2004-1	EOP	4021	31302096	Conti Clamp-in TG1C 433MHz Volvo	2
V40	Y555	2014-3	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	110,227
V40 (LCV)	Y555	2014-7	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	23
V40 XC	Y555	2014-3	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	20,179
V50	Y280	2003-11	2012-05	4021	31302096	Conti Clamp-in TG1C 433MHz Volvo	320
V60	Y352	2014-7	2017-09	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	36,855
V60	Y352	2010-9	2014-06	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	9,677
V60 Cross Country	Y352	2015-1	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	2,196
V70	Y285	2014-7	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	6,662
V70	Y285	2006-3	2008-10	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	289
V70	Y285	2008-1	2014-06	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	6,297
XC60	Y413	2014-7	2016-10	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	58,278
XC60	Y413	2008-5	2014-06	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	15,391
XC70	Y381	2014-7	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	3,692
XC70	Y381	2007-2	2014-06	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	4,125
XC90	V526	2015-1	EOP	3069	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	22,551
XC90	Y289	2015-1	EOP	3046	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	665
XC90	Y289	2002-4	2014-12	3046	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	633
XC90 (LCV)	V526	2015-6	EOP	3069	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	2
XC90 (LCV)	Y289	2014-6	EOP	3046	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	5

**Euroguide -Sensors Look Up**

**Sensors Look Up:** This list identifies which cars can be fitted with a particular Schrader referenced part number.

- 1/ Identify the Schrader Code of the sensor (After Market reference) in the first column "**Schrader Part Number**"
- 2/ In the same column identify which car manufacturer and car model the sensor is fitted on.  
-- When the sensor reference is matching the right car model, all the necessary information concerning the car and the sensor are in the following columns (same line, from left to the right).
- 3/ **Car Model Code** is the identification code of the vehicle.
- 4/ "**Start of Application**" and "**End of Application**" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.
- 5/ **OE Sensor reference:** This is car manufacturer's part number for the sensor.
- 6/ **Sensor Description:** Description of the After Market reference.
- 7/ **Direct TPMS car park in Market:** number of vehicles introduced in the reference market with direct TPMS systems using the specific sensor indicated in the OE sensor reference column.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk. This list will be regularly updated.

For further information: [tpmseuroshop.com](mailto:tpmseuroshop.com) or [aftermarket@schradereurope.com](mailto:aftermarket@schradereurope.com)

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>3000</b>							
<b>Citroen</b>							
Berlingo (LCV)	B9	2008-1	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	4,914
C4	B7	2010-6	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	43,470
C4 Picasso	B58	2006-5	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	135,427
DS4	B75	2010-12	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	20,506
DS4 (LCV)	B75	2010-12	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	46
DS5	B81	2011-6	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	12,902
DS5 (LCV)	B81	2011-6	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	10
Jumper	X2/50	2006-1	2013-11	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	7,734
<b>Peugeot</b>							
3008	T84	2008-11	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	178,923
3008 (LCV)	T84	2008-11	EOP	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	85
307	T5	2007-1	2007-12	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	119,224
308	T7	2007-4	2013-08	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	131,494
5008	T87	2009-9	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	95,827
RCZ	T75	2009-12	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	14,261
<b>3001</b>							
<b>Citroen</b>							
Jumpy	G9	2014-6	EOP	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	21,402
Jumpy Combi	G9	2014-6	EOP	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	5,165
<b>Fiat</b>							
Scudo	G9	2006-9	2013-10	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	14,943
Scudo Combi	G9	2006-9	2013-10	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	3,854
<b>3002</b>							
<b>Citroen</b>							
Berlingo	B9	2013-10	2017-01	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	23,236
Berlingo Multispace	B9	2013-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	11,677
C5	X7	2013-9	2016-09	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	24,299
C5 (LCV)	X7	2007-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	33

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
C-Elysee	M3/M4	2012-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	22,524
DS4	B75	2014-2	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	28,283
DS5	B81	2014-2	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	23,540
Jumper	X2/50	2013-12	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	10,628
Jumper Chassis	X2/50	2014-6	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	94
Jumper Combi	X2/50	2014-6	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	2,165
<b>Peugeot</b>							
207	A7	2013-9	2016-06	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	12,813
3008	T84	2013-9	2016-09	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	159,406
301	M3/M4	2012-10	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	16,694
308	T7	2013-9	2015-01	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	52,901
408	T73	2014-6	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	9,140
5008	T87	2013-9	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	61,400
5008 (LCV)	T87	2009-9	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	53
508	W2	2013-9	2017-06	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	89,302
508 (LCV)	W2	2010-9	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	31
508 RXH	W24	2013-9	2017-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	717
Partner	B9	2014-6	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	75,025
Partner Tepee	B9	2014-6	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	26,497
Partner Van	B9	2014-6	EOP	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	3,919
RCZ	T75	2013-10	2016-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	12,845
<b>3003</b>							
<b>Fiat</b>							
Scudo	G9	2013-11	2015-12	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	15,810
Scudo Chassis	G9	2014-3	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	23
Scudo Combi	G9	2013-11	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	4,323
<b>Peugeot</b>							
Expert	G9	2014-6	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	21,625
Expert Tepee	G9	2014-6	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	4,922
<b>Toyota</b>							
Proace	G9	2014-6	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	6,962
Proace Combi	G9	2014-6	EOP	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	428
<b>3004</b>							
<b>Citroen</b>							
C5	X40	2000-12	2004-07	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	71,474
C8	V3	2002-2	2005-10	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	11,912
<b>Fiat</b>							
Ulysse	V1	2002-2	2005-10	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	1,598
<b>Peugeot</b>							
607	Z8	1999-9	2004-10	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	14,903
807	V2	2002-2	2004-09	Schrader	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	12,518
<b>3005</b>							
<b>Jeep</b>							
Compass	MK49	2014-9	EOP	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	3,643
Compass		2006-5	2014-08	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	19,079
Patriot	MK74	2006-12	2014-08	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	122
Patriot		2014-9	EOP	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	17
Patriot (LCV)	MK74	2006-12	EOP	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	31
<b>3006</b>							
<b>Chrysler</b>							
300/300C	LE48	2005-6	2010-06	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	6,300
Grand Voyager	RT	2007-7	2011-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	1,670
Sebring	JS41C	2006-8	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	49
Sebring Convertible	JS27	2007-2	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	42

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>Town &amp; Country</b>	RT	2007-7	2011-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	630
<b>Dodge</b>							
Avenger	JS41D	2006-11	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	95
Caliber	PM49	2006-1	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	270
Challenger	LC22	2008-1	2010-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	59
Nitro	KA	2006-8	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	186
Nitro (LCV)	KA	2006-8	2012-06	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	9
<b>Jeep</b>							
Cherokee	KK	2007-7	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	498
Grand Cherokee	WH	2005-3	2010-06	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	5,032
Wrangler	JK72	2006-8	2010-09	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,520
Wrangler (LCV)	JK72	2006-8	EOP	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3,079
<b>Lancia</b>							
Voyager	RT	2007-7	2011-01	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,901
<b>3007</b>							
<b>Chrysler</b>							
Grand Voyager	RT	2011-1	2017-09	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	1,672
Voyager	RT	2014-6	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3,046
<b>Dodge</b>							
Caravan	RT	2011-6	2017-05	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	7
Challenger	LC22	2010-2	2017-09	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	150
Charger	LD	2010-12	2014-09	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3
Charger		2014-10	2016-06	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	1
Durango	WD75	2010-11	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	295
Journey	JC49	2014-7	2015-09	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	29
Journey		2011-1	2014-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	291
Ram	DS	2010-1	2012-12	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	4,546
<b>Fiat</b>							
Freemont	JF	2014-7	2015-09	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	11,254
Freemont		2011-3	2014-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	38,714
<b>Jeep</b>							
Grand Cherokee	WK74	2010-7	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	59,643
Grand Cherokee (LCV)	WK74	2010-5	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	47
Wrangler	JK72	2010-10	2013-12	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	28,820
Wrangler		2014-1	EOP	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	4,805
<b>Lancia</b>							
Voyager	RT, RU	2011-1	2015-10	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	571
Voyager (LCV)	RT	2011-1	EOP	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	186
<b>3008</b>							
<b>Chrysler</b>							
300	LE48	2014-6	EOP	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3
300	LX	2011-1	2016-06	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	210
300C	LX	2014-6	EOP	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	42
<b>Dodge</b>							
Viper	ZD	2013-8	2015-06	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3
<b>3009</b>							
<b>Alfa Romeo</b>							
4C	4C	2013-6	2021-03	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,154
<b>Dodge</b>							
Viper	ZD	2015-7	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	3

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>Fiat</b>							
Ducato	SEVEL X2	2014-6	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	346
Ducato	X2/50	2014-6	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	8,201
Ducato Chassis	X2/50	2014-6	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2
Ducato Combi	X2/50	2014-6	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,629
<b>Maserati</b>							
Ghibli	M157	2013-11	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	8,788
GranCabrio	M147	2015-7	2021-03	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	125
GranTurismo	M145	2014-1	2020-03	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	852
GT Coupe	M138	2014-3	EOP	Schrader	95518233/670002790	Schrader Clamp-in Gen Gamma 433MHz Maserati / Alfa Romeo	9
Levante	WM	2015-4	2021-09	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,214
Quattroporte	M156	2013-1	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,203
<b>Peugeot</b>							
Boxer	X2/50	2013-12	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	12,557
Boxer Combi	X2/50	2013-12	EOP	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	264
<b>3011</b>							
<b>Mercedes-Benz</b>							
A-Class	W176	2013-1	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,245
B-Class	W246	2013-1	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	111,773
C-Class	C204	2014-3	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	10,847
C-Class	W204	2013-1	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	18,036
C-Class Coupe	C204	2012-12	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	8,732
CL	C216	2006-7	2014-03	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	115
CL	C217	2014-4	2020-06	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,089
CLA	C117	2012-12	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	290
CLS	C218	2013-1	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,707
CLS		2009-8	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,039
E-Class	W212	2013-1	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	41,169
E-Class		2009-1	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	9,800
E-Class Coupe	C207	2009-1	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,268
GLA	X156	2014-1	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	41,118
GL-Class	X164	2009-6	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,015
GL-Class	X166	2013-1	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,700
GLK	X204	2012-12	2015-09	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	22,650
G-Wagen	G463/461	2013-1	2022-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,830
G-Wagen		2007-4	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,754
G-Wagen (LCV)	G463/461	2012-12	2022-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	17
ML-Class	W166	2011-7	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,276
R-Class	V251	2013-1	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	277
R-Class		2009-7	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,352
S-Class	W221	2013-1	2013-06	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	451
S-Class		2009-7	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,371
SL	R231	2013-1	2014-05	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,221
SL		2009-8	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,678
SLK	R172	2013-1	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	11,564
SLS	C197	2013-1	2023-09	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	35
SLS		2010-2	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,535
Sprinter	NCV3	2014-6	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	113,102
Sprinter Combi	NCV3	2013-1	EOP	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	8,956
Vito Combi	VS20	2012-12	2023-04	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	9,840
<b>3012</b>							
<b>Mercedes-Benz</b>							
V-Class	VS20	2014-3	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	18,258
V-Class	W638	2014-6	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	23

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Viano	VS20	2014-6	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	124
Viano (LCV)	VS20	2014-8	2023-07	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	342
Vito	VS20	2014-7	EOP	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	51,140
<b>3013</b>							
<b>Mercedes-Benz</b>							
A-Class	W176	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	116,334
A-Class (LCV)	W176	2014-6	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	91
B-Class (LCV)	W246	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	44
C-Class	C205	2015-1	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	1,845
C-Class	W205	2014-1	2021-03	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	261,284
C-Class (LCV)	W205	2014-7	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	10
C-Class Coupe	C205	2015-6	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	17,917
CLA	C117	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	57,202
CLS	C218	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	10,655
E-Class	C207	2014-6	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	33,302
E-Class	W212	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	79,247
GLA	X156	2014-12	2020-12	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	60,843
GLC	X253	2015-1	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	12,756
GL-Class (LCV)	X166	2014-3	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	2
GLE Coupe	C292	2015-1	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,369
GLK	X204	2015-10	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	3,440
GLK	X253	2015-10	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	3,143
GLK (LCV)	X204	2014-6	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	47
GLK (LCV)	X253	2015-10	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	1
GT	C190	2014-1	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	2,765
MLC	C292	2012-12	2019-03	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,072
ML-Class	W166	2014-7	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	27,013
ML-Class (LCV)	W166	2014-6	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	39
S-Class	W222	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	17,414
S-Class Coupe	C217	2014-7	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,127
S-Class Pullman	X222	2014-3	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	502
SL	R231	2014-6	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	2,577
SLC	C190	2015-1	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	3,441
SLK	R172	2014-12	EOP	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	8,193
<b>3016</b>							
<b>Alfa Romeo</b>							
MiTo	955	2013-8	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	270
MiTo (LCV)	955	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	7
<b>Citroen</b>							
Nemo	225	2007-10	2015-12	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	14,987
Nemo Multispace	225	2007-10	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	3,619
<b>Fiat</b>							
500	312	2015-8	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	51,524
500		2007-5	2015-07	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	133,724
500 (LCV)	312	2007-5	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	31
500C	312	2007-5	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	43,505
500L (LCV)	330	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2
Doblo	223	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1
Doblo	263	2009-12	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	87,626
Doblo Combi	263	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	964
Fiorino	225	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	3,591
Fiorino Qubo	225	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	971
Freemont (LCV)	JF	2011-3	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	25
Linea	200	2007-3	2016-03	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	42,372

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Linea	200(2)	2015-11	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1
Qubo	225	2007-10	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2,333
Strada	178	1998-9	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2,047
<b>Lancia</b>							
Delta	PK	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	5,246
<b>Opel</b>							
Combo	263	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	18,062
Combo Combi	263	2014-6	EOP	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	2,487
<b>3017</b>							
<b>Fiat</b>							
Idea	350	2003-9	2012-07	Schrader	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	320
<b>Lancia</b>							
Musa	848	2004-7	EOP	Schrader	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	355
<b>3018</b>							
<b>Ford</b>							
Econoline	VN127	2006-1	EOP	Schrader	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	17
Escape	U377	2009-1	2012-04	Schrader	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	3
Mustang (Import)	S197	2004-9	2014-04	Schrader	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	1
<b>3019</b>							
<b>Ford</b>							
Ecosport	B515	2012-7	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,552
Tourneo Courier	B460	2014-3	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	231
Transit Chassis	V348	2014-3	EOP	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	87
Transit Courier	B460	2014-3	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1,238
<b>3020</b>							
<b>Ford</b>							
Edge	U387	2014-6	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	315
Escape	C520	2012-4	2017-06	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	5
Expedition	U222(2)	2005-1	2008-11	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	63
Explorer	U502	2010-11	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,687
F-150	P415	2008-9	2014-06	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	63
F-Series	P415	2008-9	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	52
Tourneo Custom	V362	2013-4	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	3,427
Transit	V363	2013-6	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	131,510
Transit Chassis	V363	2013-6	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
Transit Combi	V348,V363	2013-6	2021-03	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	3
Transit Combi	V363	2013-6	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,859
Transit Custom	V362	2013-4	EOP	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	20,021
<b>Mazda</b>							
B-Series	J26E	2015-6	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	50
BT-50	J26E	2011-5	EOP	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	228
<b>3021</b>							
<b>Ford</b>							
B-Max	B232	2014-6	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	63,321
B-Max (LCV)	B232	2014-6	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	32
C-MAX	C344	2014-3	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	123,799
C-Max (LCV)	C344	2010-8	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	199
Ecosport	B515	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	32,154
Fiesta	B299	2014-5	2015-12	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	385,324
Fiesta Van	B299	2014-6	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	12,996
Focus	C346	2014-3	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	369,729
Focus (LCV)	C346	2010-12	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	190
Kuga	C394	2014-6	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	11
Kuga	C520	2012-11	2019-09	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	147,647

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Kuga (LCV)	C520	2012-11	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	36
Mondeo	CD391	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	114,476
Mondeo (LCV)	CD391	2013-9	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	13
Mustang	S550	2014-5	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	3,354
Ranger	P375	2014-6	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	22,299
Tourneo Connect	V408	2014-3	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	15,327
Tourneo Courier	B460	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	11,077
Transit	V347	2014-6	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	88
Transit	V348	2014-6	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	19
Transit Connect	V408	2014-3	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	81,291
Transit Courier	B460	2014-10	EOP	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	36,306
<b>3023</b>							
<b>Ford</b>							
Edge	CD539	2014-8	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	4,950
Edge	CD389	2015-1	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	5,158
Galaxy	CD390	2015-1	2022-06	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	18,194
Galaxy (LCV)	CD390	2014-11	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	29
S-MAX	CD539	2015-1	2021-06	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	37,697
S-MAX	CD389	2015-1	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	35,982
S-Max (LCV)	CD539	2014-10	EOP	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	75
<b>3024</b>							
<b>Ford</b>							
Mustang	S197	2014-5	EOP	Schrader	DR3V-1A180-BA	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	63
Mustang		2004-9	2014-04	Schrader	DR3V-1A180-BA	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	117
<b>3026</b>							
<b>Chevrolet</b>							
Volt	D1JCI	2010-11	EOP	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,155
<b>Opel</b>							
Ampera	D1JOI	2011-9	EOP	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	776
Astra	GM P3400	2009-10	2011-09	Schrader	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	6,876
Astra		2011-9	2014-05	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	13,365
Cascada	D1AO	2013-1	2014-05	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,148
Insignia	GM G3700	2008-10	2011-09	Schrader	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	28,654
Insignia		2011-9	2014-04	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	32,336
Zafira Tourer	GM P3470	2011-9	2014-05	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	12,549
Zafira Tourer (LCV)	GM P3470	2011-9	EOP	Schrader	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2
<b>3027</b>							
<b>Opel</b>							
Adam	GM 4403	2013-1	2014-07	Schrader	13581562	Schrader Snap-in GEN4 type 433MHz GM	407
Corsa Van	GM S4400	2014-6	EOP	Schrader	13581562	Schrader Snap-in GEN4 type 433MHz GM	4,557
<b>3031</b>							
<b>Opel</b>							
Astra	GM A3300	2004-1	2010-12	Schrader	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,865
Vectra	GM Z3200	2002-1	2008-09	Schrader	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	34,385
Zafira	GM A3370	2011-7	2016-09	Schrader	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	8,384
Zafira		2009-1	2011-06	Schrader	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2,865
Zafira (LCV)	GM A3370	2005-4	2008-12	Schrader	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	16
<b>3033</b>							
<b>Opel</b>							
Astra	GM P3400	2014-6	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	316,958
Astra Van	D2JO.GM P3400	2014-6	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	21
Astra Van	GM P3400	2014-6	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	125
Cascada	D1AO	2014-6	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	4,915
Insignia	GM G3700	2014-5	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	69,563

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Zafira Tourer	GM P3470	2014-6	EOP	Schrader	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	42,821
<b>3037</b>							
<b>Nissan</b>							
Primera	ED	2001-12	2007-05	Schrader	40700 AV600	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Nissan	1,350
<b>3038</b>							
<b>Infiniti</b>							
M	L53E	2009-12	EOP	Schrader	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	100
<b>Nissan</b>							
370Z	C53D	2008-10	EOP	Schrader	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,765
370Z	RC53D	2009-3	EOP	Schrader	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	684
GT-R	D52E	2007-9	2015-12	Schrader	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,684
Murano	P42D	2007-10	EOP	Schrader	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,870
Navara	H60A	2014-9	2020-06	Schrader	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	224
Navara	D22,H61B	2014-3	EOP	Schrader	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,175
<b>3039</b>							
<b>Infiniti</b>							
EX	P53B	2007-10	2016-03	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	95
FX	P53C	2014-9	2020-09	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	693
FX		2008-3	2014-08	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,550
G	L53A	2013-4	2019-01	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	7
G		2006-8	2013-03	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	931
Q70	L53E	2013-11	EOP	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	825
QX50	P53B	2014-6	EOP	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,367
QX50	P53B(2)	2015-11	EOP	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	29
QX70	P53C	2014-6	EOP	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	4,259
<b>Renault</b>							
Koleos	H45	2008-2	2013-12	Schrader	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	398
<b>3040</b>							
<b>Renault</b>							
Clio	X85	2005-4	2014-05	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	15,867
Modus	J77	2004-5	EOP	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	2,644
<b>3041</b>							
<b>Dacia</b>							
Dokker	K67	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	30,997
Dokker Van	F67	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	22,641
Duster	H79	2010-2	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	261,294
Duster Pickup	H79	2015-10	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	9
Duster Pro	H79	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,443
Lodgy	J92	2012-1	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	47,412
Lodgy (LCV)	J92	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3
Logan	L52	2012-11	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	70,081
Logan MCV	K52	2013-4	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	51,182
Logan Van	F90	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3
Sandero	B52	2012-10	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	233,269
Sandero Pro	B52	2012-10	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	65
<b>Mercedes-Benz</b>							
Citan	VS10	2012-9	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	24,527
Citan Combi	VS10	2014-1	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,144

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>Nissan</b>							
Terrano	H79N	2014-3	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	10,906
<b>Opel</b>							
Movano	X62	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	14,711
Movano Combi	X62	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	490
Vivaro	X82	2014-9	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	45,573
Vivaro	X83	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	180
Vivaro Combi	X82	2014-9	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,616
Vivaro Combi	X83	2014-3	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	54
<b>Renault</b>							
Captur	J87	2013-1	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	231,820
Captur (LCV)	J87	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	86
Clio Van	X85	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Clio Van	X98	2012-7	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,220
Kangoo	X61	2007-10	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	106,562
Kangoo		2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	68,140
Kangoo Passenger	X61	2007-10	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	31,420
Master	X62	2009-11	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	96,315
Master Passenger	X62	2009-11	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	2,977
Symbol/Thalia	L35 (R)	2014-6	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Symbol/Thalia	L52	2013-4	2020-03	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	28,338
Trafic	X82	2014-3	2026-03	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	85,398
Trafic Passenger	X82	2014-3	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	12,692
Twingo	X07	2014-3	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	145,826
Twingo	X44	2007-1	2016-09	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	10
Twingo Van	X07	2014-10	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,984
<b>Smart</b>							
forfour	A453	2014-7	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	56,722
Fortwo	A452	2014-4	2021-03	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	89,549
Fortwo	C453	2014-3	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	78,636
Fortwo (LCV)	C453	2014-8	EOP	Schrader	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	30
<b>3042</b>							
<b>Renault</b>							
Espace	J81	2002-7	EOP	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	55,787
Espace (LCV)	J81	2002-7	EOP	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	5
Grand Espace	J81	2002-7	EOP	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	4,487
Laguna	X74	2000-12	2007-09	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	132,224
Megane	X64	1997-1	2002-10	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	10,578
Scenic	J64	1997-1	2003-06	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	10,578
Vel Satis	X73	2001-9	2009-11	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	130,486
<b>3046</b>							
<b>Volvo</b>							
XC90	Y289	2015-1	EOP	Schrader	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	665
XC90		2002-4	2014-12	Schrader	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	633
XC90 (LCV)	Y289	2014-6	EOP	Schrader	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	5
<b>3047</b>							
<b>Volkswagen</b>							
Transporter	VN760	2015-9	EOP	Schrader	2N0907251	Schrader Snap-in Faraday 433MHz VW	12,026
Transporter Shuttle	VN760	2015-9	EOP	Schrader	2N0907251	Schrader Snap-in Faraday 433MHz VW	23
<b>3049</b>							
<b>Buick</b>							
Park Avenue	G-CAR	1997-1	2004-06	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	32

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>Cadillac</b>							
CTS	GMX206	2008-1	EOP	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	87
CTS	GMX226	2010-6	EOP	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	175
Escalade	GMT926	2005-12	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,338
Escalade		2014-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	160
Escalade	K2UL	2014-1	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	660
Escalade (LCV)	GMT926	2005-12	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	8
SRX	GMT166	2009-7	EOP	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	3,216
SRX	GMT265	2005-6	2009-02	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	36
XTS	P1LL	2012-5	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	4
<b>Chevrolet</b>							
Aveo	G1JC	2014-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,490
Aveo	G1SC	2010-11	2016-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	16,025
Aveo	T250	2014-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
Captiva	C100	2006-6	2014-05	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	7,766
Captiva			EOP	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	2,296
Cobalt	G1LC	2013-2	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	23,701
Cruze	D1JC	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	816
Cruze	D1WC	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,444
Express	GMT610	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	73
Express (PC)	GMT610	2002-7	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	2
Malibu	V300	2011-7	2014-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	16
Malibu		2010-7	2011-06	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	2,561
Matiz	M100	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	12,805
Matiz	M200	2014-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	43
Orlando	D1NC	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	4,620
Orlando	J309	2010-9	2017-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	20,322
Orlando (LCV)	D1NC	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	3
Silverado	K2XC	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	16
Spark	M1JC	2009-7	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	4,130
Suburban	GMT931	2006-3	2008-07	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	4
Tracker	G1UC	2014-1	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	6,421
Trax	G1UC	2012-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	9,173
<b>Daewoo</b>							
Gentra	J200	2013-8	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	28,787
Nexia	T-CAR	2014-6	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	48,228
Nexia	T	2014-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	12,791
<b>GMC</b>							
Sierra	K2XG	2013-4	2019-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	23
Yukon	GMT922	2005-12	2013-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	244
Yukon		2014-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	18
Yukon	K2UG	2014-3	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
<b>Hummer</b>							
H2	H2	2002-4	2008-12	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	189
H3	GMT345	2005-3	2012-01	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	95
H3 (LCV)	GMT345	2005-3	2012-01	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	95
<b>Opel</b>							
Antara	C105	2010-11	EOP	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	630
Antara		2006-8	2010-11	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	687
Mokka	G1UO	2012-6	2015-08	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	136,340
<b>3053</b>							
<b>Cadillac</b>							
STS	GMX295	2005-6	2011-04	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	9
XLR	GMX215	2003-5	2009-04	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	8

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>Chevrolet</b>							
Colorado (LCV)	GMT355	2003-10	EOP	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	63
Corvette	GMX245	2004-7	2010-01	Schrader	25758221	Schrader Clamp-in Gen J 433MHz GM	1,507
<b>3054</b>							
<b>Cadillac</b>							
ATS	A1BL	2014-7	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	226
ATS	A1SL	2012-7	2018-03	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	413
CTS	A1LL	2013-9	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	392
<b>Chevrolet</b>							
Camaro	GMX521	2010-11	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	390
Colorado	GMI700	2014-6	EOP	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	453
Corvette	GMX245	2010-2	2014-12	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	847
<b>3055</b>							
<b>Cadillac</b>							
CTS	GMX322	2006-1	2007-06	Schrader	25774007	Schrader Clamp-in Gen J 433MHz GM	371
<b>Chevrolet</b>							
Trailblazer (LCV)	GMT360	2001-1	EOP	Schrader	25774007	Schrader Clamp-in Gen J 433MHz GM	3
<b>3056</b>							
<b>Hyundai</b>							
Veloster	FS	2011-2	EOP	Schrader	52933-2V100	Schrader Snap-in GEN4 type 433MHz HKMC	2,951
<b>3057</b>							
<b>BMW</b>							
7-Series	G11	2015-7	2022-06	Schrader	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	1,364
C-MPV	F46	2015-7	2022-03	Schrader	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	15,197
X6	F16	2015-8	2021-07	Schrader	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	7,267
X6 (LCV)	F16	2015-10	EOP	Schrader	6872774	Schrader Clamp-in Gen Delta 433MHz VDA BMW	1
<b>3058</b>							
<b>Lotus</b>							
Elise	Monza	2008-1	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	788
Evora	Eagle	2010-1	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	454
Exige	Monza	2008-1	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	569
<b>Saab</b>							
Saab 9-3	SB440	2014-6	EOP	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	91
<b>3059</b>							
<b>Hyundai</b>							
i10	IA	2013-11	EOP	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	164,730
<b>Kia</b>							
Soul	PS	2013-11	EOP	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	28,806
Soul (LCV)	PS	2013-10	EOP	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	11
<b>3060</b>							
<b>Hyundai</b>							
i20	GB	2014-1	EOP	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	123,727
i20	GB,IB	2014-11	EOP	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	89,699
i20 (LCV)	GB	2014-11	EOP	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	17
i20 (LCV)	IB	2015-1	EOP	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	34
<b>3062</b>							
<b>Chevrolet</b>							
Malibu	V300	2014-7	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	38
Niva	2123	2014-6	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	27,283
<b>Mahindra</b>							
B-CUV	S101	2015-9	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	4
Bolero	CL/MM	2014-6	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	6
Bolero	U301	2015-7	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	5
NC	CL/MM	2014-6	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	3

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Scorpio	MI	2014-6	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	130
Scorpio	W105	2014-6	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	51
Thar	CL/MM	2014-6	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	13
XUV500	W201	2014-6	EOP	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	50
<b>Opel</b>							
Adam	GM 4403	2014-8	2015-08	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	53,068
Adam		2015-8	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	19,000
Adam (LCV)	GM 4403	2014-3	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	2
Corsa	GM 4530	2014-11	2015-02	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	53,952
Corsa		2015-3	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	4,848
Corsa Van	GM 4530	2015-3	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	5,943
Meriva	GM S4470	2014-8	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	53,616
Meriva (LCV)	GM S4470	2014-6	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	61
Mokka	G1UO	2015-9	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	37,713
Mokka (LCV)	G1UO	2014-6	EOP	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	13
<b>3063</b>							
<b>Opel</b>							
Karl	M2JO	2015-1	EOP	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM	26,758
<b>3064</b>							
<b>Subaru</b>							
C-Concept	VL9	2014-6	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	13,817
Forester	FM5	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	24,141
Forester (LCV)	FM5	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	25
Impreza	MF1	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6,525
Impreza	ZR1	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	165
Impreza (LCV)	MF1	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	5
Justy	D71A	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1
Legacy	04AL	2014-10	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	10,384
Legacy (LCV)	04AL	2015-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2
Outback	04AL	2014-11	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,370
Outback	BF4	2014-9	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	5,506
Trezia	217A	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,196
Tribeca	00X	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	20
WRX	MF1	2014-3	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	401
WRX	VL9	2014-3	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,274
XV	MF1	2014-1	EOP	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	15,660
<b>3066</b>							
<b>Dodge</b>							
Journey	JC49	2015-10	EOP	Schrader	Info not available	Schrader Snap-in Faraday 433MHz Chrysler	10
<b>Fiat</b>							
Freemont	JF	2015-10	EOP	Schrader	Info not available	Schrader Snap-in Faraday 433MHz Chrysler	3,753
<b>3068</b>							
<b>Ssangyong</b>							
Actyon Sports	Q150	2014-3	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	534
Actyon SUT	Q150	2014-11	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	3
Actyon SUT	Q100	2014-3	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	86
C-CUV	X100	2015-5	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	3,245
Korando	C200/AS11	2013-8	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	42
Korando C	C200/AS11	2013-8	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1,327
Korando C (LCV)	C200/AS11	2013-8	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	5
Korando Sports	Q150	2014-11	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	815
Kyron	D100	2014-6	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	7,677
New Actyon	C200/AS11	2014-6	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	12,516
Nomad	Q150	2014-2	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	575

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Rexton	Y200	2014-5	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	2,818
Rexton (LCV)	Y200	2014-5	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	43
Rexton SC	Y200	2014-5	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	14
Rodius	A100	2014-5	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1,997
Rodius (LCV)	A100	2014-5	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	4
Tivoli	X100	2015-1	EOP	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	4,525
<b>3069</b>							
<b>Volvo</b>							
XC90	V526	2015-1	EOP	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	22,551
XC90 (LCV)	V526	2015-6	EOP	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	2
<b>3071</b>							
<b>Chevrolet</b>							
Volt	D2JCI	2015-6	2020-09	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	133
<b>Opel</b>							
Ampera	D2JCI	2015-1	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	14
Astra	D2JO	2015-8	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	3,511
Astra (LCV)	D2JO	2015-1	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	1
Astra Van	D2JO	2015-1	EOP	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	1
<b>3073</b>							
<b>Renault</b>							
Clio	X98	2014-6	EOP	Schrader	40700 9987R	Schrader Snap-in Faraday 433MHz Renault T4	358,910
Clio Van	X10,X98	2014-3	EOP	Schrader	40700 9987R	Schrader Snap-in Faraday 433MHz Renault T4	124
<b>4001</b>							
<b>Alfa Romeo</b>							
8C Competizione	920	2007-1	EOP	Huf	24 88 87	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	85
<b>Audi</b>							
A6 Allroad	AU566	2000-4	2005-08	Huf	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	93
A8	AU631	1999-9	2010-07	Huf	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	8,960
<b>Ferrari</b>							
550 Maranello	F133	2002-3	EOP	Huf	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	315
612 Scaglietti	F137	2004-4	2011-06	Huf	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	315
F430	F131	2005-5	2007-06	Huf	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	31
F599 GTB	F141	2004-3	EOP	Huf	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	65
<b>Maserati</b>							
GT Coupe	M145	2002-1	2009-06	Huf	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	158
Quattroporte	M139	2004-4	2009-12	Huf	18 51 89	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	637
<b>Maybach</b>							
57/62	W240	2002-9	EOP	Huf	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	53
<b>Mercedes-Benz</b>							
CL	C215	1999-7	2005-09	Huf	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	177
CLS	C219	2004-10	2005-06	Huf	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	295
S-Class	W220	1999-7	2005-09	Huf	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	886
SL	R230	2001-1	2005-05	Huf	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	886
SLR	C199	2004-1	2010-12	Huf	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	555
<b>Porsche</b>							
911	997	2004-7	2008-03	Huf	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,720
Boxster	987	2004-11	2008-10	Huf	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,433
Carrera GT	980	2003-7	2006-04	Huf	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1
Cayman	987	2005-1	2008-01	Huf	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	851

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>Volkswagen</b>							
Phaeton	VW611	2002-4	2007-05	Huf	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	2,289
<b>4002</b>							
<b>BMW</b>							
3-Series	E46	1997-5	2004-12	Huf	36 11 2 360 420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	2,966
5-Series	E39	1998-9	2003-07	Huf	36 11 8 378 682	Beru-Huf Clamp-in Separate valve G1 433MHz BMW	1,780
7-Series	E39	1998-9	2001-10	Huf	36 11 2 360 420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,890
7-Series	E65	2001-11	2003-11	Huf	36 11 2 360 420	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	1,890
<b>4003</b>							
<b>BMW</b>							
X5	E53	1999-10	2004-04	Huf	36 14 6 752 128	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz BMW	1,890
<b>Land Rover</b>							
Range Rover (LCV)	L322	2002-3	2003-02	Huf	YDB 0000 60	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Land Rover	32
<b>4005</b>							
<b>Ferrari</b>							
Enzo	Enzo	2003-9	2004-12	Huf	193867	Beru-Huf Clamp-in Separate valve G1 plus 433MHz Ferrari	96
<b>Porsche</b>							
Cayenne	E2	2002-12	2006-12	Huf	955 361 661 01	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Porsche	1,890
<b>Volkswagen</b>							
Touareg	VW516	2002-10	2006-12	Huf	7L0 907 275 B	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz VW/Porsche	3,433
<b>4007</b>							
<b>Alpina</b>							
Alpina 3	E90	2007-3	2009-09	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	95
Alpina 6	E63	2006-3	2010-12	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	3
<b>BMW</b>							
3-Series	E90/E91/E92/E93	2006-6	2009-09	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	63
5-Series	E60/E61/F07	2006-3	2010-08	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,260
6-Series	E63	2006-3	2010-12	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	593
7-Series	E65/E66	2006-3	2008-07	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,890
7-Series	F01/F02/E68	2008-9	2010-08	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	1,890
X3	E83	2003-3	2010-08	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	630
X5	E70	2006-10	2010-09	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	4,450
X6	E71	2007-12	2011-10	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	593
Z4	E89	2009-5	2010-08	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	30
Z4 Coupe	E86	2006-4	2008-08	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	63
<b>Mini</b>							
Clubman	R55	2007-8	2009-09	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	61
<b>Rolls-Royce</b>							
Ghost	RR04	2009-12	2010-08	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	367
Phantom	RR01	2007-9	2011-12	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	110
Phantom Drophead Coupe	RR02	2006-8	EOP	Huf	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	110
<b>4009</b>							
<b>Aston Martin</b>							
Rapide	VH400	2010-1	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	319
V12 Zagato	Zagato	2012-9	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1
V8 Vantage	AM305	2005-7	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	702
V8 Vantage	VH600	2014-1	2021-06	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	131
Vanquish	AM310	2012-6	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	403
Virage	AM803	2011-5	2017-08	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1
<b>Audi</b>							
A4	AU461/AU471	2004-11	2007-10	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,986
A4 Cabrio	AU465/AU475	2006-1	2008-07	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597
A6	AU561	2009-6	2011-03	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597
A6		2004-5	2009-06	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
A6	AU571	2011-1	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	44,838
A6 Allroad	AU566	2009-6	2011-08	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	171
A6 Allroad		2006-5	2009-06	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	161
A6 Allroad	AU572/4	2012-1	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,924
A8	AU641	2009-11	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	8,863
Q7	AU716	2014-6	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,504
Q7		2006-3	2009-06	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,986
Q7		2009-6	2014-05	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,695
R8	AU714	2015-4	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	534
R8		2009-6	2015-03	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,100
R8		2007-4	2009-06	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	597
<b>Bentley</b>							
Azure	BY824	2006-6	2011-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5
Azure	BY835	2013-10	2020-10	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	130
Continental	ROLLS ROYCE	2014-3	EOP	Huf	4F0 907 275 B	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	1
Continental Flying Spur	BY611	2005-3	2010-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15
Continental Flying Spur	BY621	2010-1	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,592
Continental GT	BY624	2014-3	EOP	Huf	4F0 907 275 B	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	1,351
Continental GTC	BY615	2006-12	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,443
Continental GTC	BY625	2011-11	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,621
E-CUV	BY716	2014-11	2022-10	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	369
Mulsanne	BY831	2009-9	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,596
<b>Bugatti</b>							
Veyron	BG824	2005-9	2011-11	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3
<b>Ferrari</b>							
California	F149	2014-11	EOP	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	442
California		2008-7	2014-10	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	3,087
F12	F152	2012-10	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,256
F430	F131	2007-7	2009-12	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	30
F430 Scuderia	F131	2007-7	2012-06	Huf	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	63
F458	F142	2009-12	EOP	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	7,716
FF	F151	2011-6	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	928
LaFerrari	F150	2013-7	EOP	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	164
<b>Lamborghini</b>							
Aventador	LB834	2011-5	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	726
Aventador	LB734	2014-3	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	326
Gallardo	LB714	2010-2	2013-05	Huf	4F0 907 275 D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	877
Gallardo		2007-6	2010-01	Huf	4F0 907 275 D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	605
Gallardo	LB724	2013-6	2021-03	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	774
Huracan	LB724	2014-3	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	436
Huracan	LB624	2014-3	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	470
Murcielago	LB824	2010-11	EOP	Huf	4F0 907 275 D	Beru-Huf Clamp-in Separate valve G2.3 433MHz VW/Porsche	6
<b>Maserati</b>							
GranCabrio	M147	2009-9	2015-06	Huf	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	211
GT Coupe	M145	2009-7	2013-12	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	443
Quattroporte	M139	2010-1	EOP	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	630
<b>McLaren</b>							
MP4-12C	P11	2011-4	EOP	Huf	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	546
P1	P12	2013-1	EOP	Huf	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	28
<b>Porsche</b>							
911	991	2011-12	2015-08	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	22,530
911	997	2008-4	2011-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,587
918 Spyder	918	2013-9	2014-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
918 Spyder		2015-1	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	62
Boxster	981	2012-1	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	9,801

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Boxster	987	2008-11	2011-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,451
Cayenne	E2	2007-1	2010-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,865
Cayenne		2010-6	2014-05	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	26,159
Cayenne (LCV)	E2	2010-3	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	10
Cayman	981	2013-3	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,645
Cayman	987	2009-2	2013-02	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,515
Panamera	970	2009-9	2013-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15,117
<b>Tesla</b>							
Roadster	DarkStar	2008-3	2010-12	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
<b>Volkswagen</b>							
Phaeton	VW611	2010-6	EOP	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,086
Phaeton		2007-6	2010-05	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,399
Touareg	VW516	2007-1	2010-05	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,433
Touareg	VW526	2010-1	2014-07	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,003
Touareg (LCV)	VW526	2010-3	2014-07	Huf	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5
<b>4010</b>							
<b>Alpina</b>							
Alpina 3	E90	2009-9	2012-12	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	26
Alpina 5	F10	2010-1	2014-02	Huf	36 10 6 790 054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	142
Alpina 6	F12	2010-12	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	21
Alpina 7	F01	2010-9	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	13
XD3	F25	2010-9	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	8
<b>BMW</b>							
1-Series	E88/E82	2009-9	2011-07	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	630
3-Series	E90	2014-3	EOP	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	298
3-Series	E90/E91/E92/E93	2009-9	2012-06	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	63
5-Series	F10	2010-9	EOP	Huf	36 10 6 790 054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	33,861
5-Series GT	F07	2010-9	2014-02	Huf	36 10 6 790 054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	534
6-Series	F12	2011-3	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	358
6-Series Gran Coupe	F06	2011-3	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	314
7-Series	F01	2014-6	EOP	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	6,551
X1	E84	2009-9	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	4,451
X3	F25	2010-11	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	5,597
X5	E70	2010-3	EOP	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	9,929
Z4	E89	2010-9	2014-02	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	522
<b>Mini</b>							
Clubman	R55	2009-8	EOP	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	4,599
Clubman (LCV)	R55	2014-6	EOP	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	17
Clubvan	R55	2012-7	2015-06	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	168
Countryman	R60	2010-8	2014-06	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	75,874
Coupe	R58	2011-7	2014-06	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	321
Paceman	R61	2012-11	2014-06	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,780
Roadster	R59	2011-12	2014-06	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	490
<b>Rolls-Royce</b>							
Phantom	RR01	2012-1	2016-09	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	69
Phantom Coupe	RR02	2014-6	EOP	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	30
Wraith	RR04	2014-3	EOP	Huf	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	604
<b>4011</b>							
<b>Volkswagen</b>							
CC	VW464	2014-6	EOP	Huf	3AA 907 275 B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	1,204
Passat	VW471	2010-8	2014-07	Huf	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	5,299
Passat CC	VW464	2008-5	EOP	Huf	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	480
Tiguan	VW316	2015-1	EOP	Huf	3AA 907 275 B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	177,019
Tiguan		2011-5	EOP	Huf	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	2,808

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Tiguan (LCV)	VW316	2007-8	EOP	Huf	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	18
Touran (LCV)	VW368	2010-7	EOP	Huf	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	38
<b>4012</b>							
<b>Audi</b>							
A3 Sportback	AU370	2012-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	30,462
A3 Sportback (LCV)	AU370	2012-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
A4	AU481	2015-1	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	91,270
A4	AU491	2014-10	2021-10	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,911
A4 (LCV)	AU481	2014-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	25
A4 Allroad	AU486	2009-3	2015-12	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,524
A5	AU484	2006-12	2015-06	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,679
A5 Cabrio	AU485	2008-11	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,669
A5 Sportback	AU483	2009-7	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,213
A5 Sportback (LCV)	AU483	2014-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A6 (LCV)	AU571	2011-1	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4
A7	AU573	2010-9	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,343
Q3	AU316	2011-7	2018-03	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	24,277
Q3 (LCV)	AU316	2011-7	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
Q5	AU416	2008-9	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,022
Q5 (LCV)	AU416	2008-9	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Q7	AU726	2014-6	2021-12	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,687
Q7 (LCV)	AU726	2014-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
R8	AU724	2015-4	2023-09	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	204
TT	AU334	2014-2	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,084
<b>Porsche</b>							
911	991	2015-9	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,460
918 Spyder	PO815	2014-3	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	117
Cayenne	E2	2014-5	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,275
Macan	PO416	2013-11	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	40,755
Panamera	970	2014-1	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,112
<b>Skoda</b>							
Citigo	SK120	2011-10	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,274
Fabia	SK250	2014-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,594
Fabia	SK260	2013-11	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,602
Fabia Van	SK250	2014-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	33
Fabia Van	SK260	2013-11	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	56
Octavia	SK371	2012-11	2019-06	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	31,442
Octavia (LCV)	SK371	2012-11	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Rapid	SK251/1	2012-9	2020-04	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,316
Rapid Spaceback	SK253/1	2013-10	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,840
Roomster (LCV)	SK258	2006-4	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11
Superb (LCV)	SK461	2008-3	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Yeti	SK316	2009-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,269
Yeti (LCV)	SK316	2009-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
<b>Volkswagen</b>							
Amarok	VN817	2009-11	2017-12	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,337
Caravelle	VN750	2003-12	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,070
Eos	VW465	2006-2	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	816
Golf	VW360	2014-5	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,923
Golf	VW370	2012-8	2018-06	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	211,922
Golf (LCV)	VW370	2012-8	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	83
Golf Plus	VW379	2014-2	2019-01	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	41,657
Golf Plus (LCV)	VW379	2014-2	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18
Golf Sportsvan	VW379	2014-3	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	20,423

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Golf Sportsvan (LCV)	VW379	2014-4	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Golf SV	VW379	2014-3	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,256
Jetta	VW361	2010-7	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,479
New Beetle	VW324	2011-8	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,518
New Beetle Convertible	VW325	2012-9	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,677
Passat	VW471	2014-8	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,166
Passat CC	VW464	2014-9	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,995
Scirocco	VW364	2008-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,550
Scirocco (LCV)	VW364	2008-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Sharan	VW428	2010-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13,029
Sharan (LCV)	VW428	2010-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
Touareg	VW526	2014-8	2017-09	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,787
Transporter	VN750	2003-3	2017-03	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	30,692
Transporter Shuttle	VN750	2014-6	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	68
Up!	VW120	2011-8	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	53,001
Up! (LCV)	VW120	2011-8	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
XL1	VW019	2013-8	EOP	Huf	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
<b>4015</b>							
<b>Lancia</b>							
Flavia	JS27	2010-10	EOP	Conti	68078768AA	Conti Clamp-in TG1C 433MHz Chrysler	47
<b>4016</b>							
<b>Alfa Romeo</b>							
Giulia	UT	2014-4	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	6,517
Giulia (LCV)	UT	2014-4	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	1
<b>Chrysler</b>							
200	UF	2015-2	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	92
<b>Jeep</b>							
B-CUV	520	2014-10	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	29,600
Renegade	520	2014-3	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	38,155
<b>Lancia</b>							
Flavia	UF	2014-2	EOP	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	413
<b>4019</b>							
<b>Jaguar</b>							
F-Type	X152	2012-10	EOP	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	10,061
XJ	X351	2014-6	EOP	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	3,335
<b>Land Rover</b>							
Defender	L316	2014-6	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	12,701
Defender (LCV)	L316	2014-6	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	2,881
Discovery	L319	2009-9	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	4,525
Discovery (LCV)	L319	2009-9	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	63
Discovery Sport	L550	2014-1	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	43,538
Freelander	L359	2014-3	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	1,293
Freelander	L550	2006-10	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	7,377
Freelander (LCV)	L550	2006-10	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	39
Range Rover	L405	2010-1	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	4,839
Range Rover (LCV)	L405	2014-6	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	38
Range Rover (LCV)		2010-1	2022-04	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	19
Range Rover Evoque	L538	2014-3	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	83,955
Range Rover Evoque		2012-1	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	77,888
Range Rover Evoque (LCV)	L538	2011-7	2018-09	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	124
Range Rover Sport	L494	2014-3	EOP	Conti	LR058023	Conti Clamp-in TG1C 433MHz Ford	39,992
<b>4021</b>							
<b>Ford</b>							
Galaxy	CD340	2015-1	EOP	Conti	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	6,261

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Galaxy	CD340	2006-1	2014-12	Conti	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	5,276
Mondeo	CD345	2007-1	2015-03	Conti	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	1,260
S-MAX	CD340	2006-2	EOP	Conti	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	5,747
S-Max (LCV)	CD340	2006-2	EOP	Conti	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	21
<b>Volvo</b>							
C30	Y279	2006-9	2012-12	Conti	31302096	Conti Clamp-in TG1C 433MHz Volvo	228
C70	Y281	2006-3	EOP	Conti	31302096	Conti Clamp-in TG1C 433MHz Volvo	27
S40	Y276	2004-1	EOP	Conti	31302096	Conti Clamp-in TG1C 433MHz Volvo	2
V50	Y280	2003-11	2012-05	Conti	31302096	Conti Clamp-in TG1C 433MHz Volvo	320
<b>4023</b>							
<b>Jaguar</b>							
XF	X250	2007-11	EOP	Conti	C2C41655	Conti Clamp-in TG1B 433MHz Ford	36,240
XJ	X350	2003-5	2009-09	Conti	C2C41655	Conti Clamp-in TG1B 433MHz Ford	1,796
XK	X150	2006-1	2014-07	Conti	C2C41655	Conti Clamp-in TG1B 433MHz Ford	2,739
X-Type	X400	2007-1	EOP	Conti	C2C41655	Conti Clamp-in TG1B 433MHz Ford	1,197
<b>Land Rover</b>							
Discovery (LCV)	L319	2004-7	2009-09	Conti	LR031712	Conti Clamp-in TG1B 433MHz Ford	103
Range Rover	L322	2005-1	2009-12	Conti	LR031712	Conti Clamp-in TG1B 433MHz Ford	1
Range Rover (LCV)	L322	2005-1	2009-12	Conti	LR031712	Conti Clamp-in TG1B 433MHz Ford	21
<b>4026</b>							
<b>Hyundai</b>							
i10	IA,PA	2007-10	EOP	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	5
i10	PA	2014-3	EOP	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	541
i10 (LCV)	PA	2014-3	EOP	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	5
i30	FD	2007-10	EOP	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	2,436
<b>4027</b>							
<b>Hyundai</b>							
Accent	MC	2014-6	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	2
Accent	RB	2014-3	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	16,993
B-CUV	GC	2015-4	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	7,851
i20	PB	2008-8	2014-06	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	12,454
ix20	JC	2010-9	2013-09	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	49,866
ix20 (LCV)	JC	2010-9	2013-09	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	11
Solaris	RB	2014-3	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	156,020
Sub-Compact SUV	IB	2015-5	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	19,487
<b>Kia</b>							
Optima	TF	2011-9	2013-08	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	7,365
Sorento	XM	2009-5	2012-09	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	10,759
Venga (LCV)	YN	2010-2	EOP	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	16
<b>4028</b>							
<b>Alfa Romeo</b>							
Spider	J12A	2015-4	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	714
<b>Mazda</b>							
2	J03	2014-5	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	52,985
2	J64F	2007-12	EOP	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	15,925
2	J03W	2014-1	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	57,971
2 (LCV)	J03	2014-5	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	7
3	J68C	2009-6	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	1,058
5	J74G	2010-7	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	10,126
6	J61A	2007-8	2012-08	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	352
6	J71E	2013-3	2018-09	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	47,501
6 (LCV)	J71E	2014-6	EOP	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	11
CX-5	J53C	2011-11	EOP	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	101,961
CX-5 (LCV)	J53C	2011-11	EOP	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	19

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
CX-7	J31H	2009-6	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	158
CX-9	J50C	2010-8	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	527
MX-5	J04C	2014-3	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	5,642
MX-5		2010-3	2014-02	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	3,368
MX-5	J12A	2015-10	EOP	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	564
<b>4029</b>							
<b>Peugeot</b>							
iOn	S3	2014-6	EOP	Conti	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	914
iOn (LCV)	S3	2014-6	EOP	Conti	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	21
<b>4030</b>							
<b>Nissan</b>							
Atleon	F91A	2014-6	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	181
Atleon	F91G	2014-1	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	1,646
Cabstar	F91A	2014-6	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	5,330
Cabstar E	F91A	2014-6	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	1,234
Frontier	H60A	2014-9	2023-03	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	48
NP300	H60A	2014-9	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	590
NV300	X82	2014-9	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	9,082
NV300 Combi	X82	2014-9	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	1,004
NV400	X62	2014-6	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	3,950
NV400 Combi	X62	2014-6	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	358
Primastar	X83	2014-6	EOP	Conti	(blank)	Conti Clamp-in TG1C 433MHz Nissan	320
<b>4031</b>							
<b>Citroen</b>							
C4	B5	2004-11	2008-06	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,978
C5	X3/X40	2004-8	2007-12	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	93,511
C5	X7	2008-1	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	70,666
C6	X6	2005-9	2012-12	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,489
C8	V3	2014-7	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	15
C8		2005-9	2014-06	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	328
<b>Fiat</b>							
Ulysse	V1	2001-1	2010-10	Conti	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	796
<b>Lancia</b>							
Thema	LX	2011-1	EOP	Conti	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	4,697
<b>Peugeot</b>							
1007	PF1	2005-1	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,260
1007	A08	2014-3	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1
207	A7	2005-11	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	4,245
307	T5	2003-11	2006-12	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	84,053
407	D2	2004-1	2006-02	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	238,449
508	W2	2010-11	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	86,651
508 RXH	W24	2012-1	EOP	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	18
607	Z8	2004-10	2009-03	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	10,134
807	V2	2004-10	2014-06	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	13,867
<b>4032</b>							
<b>Nissan</b>							
Almera	LB1A	2013-5	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	76,436
C-Hatch	B12L	2014-10	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	73,215
Note	J02C	2013-8	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	85,393
Note (LCV)	J02C	2012-3	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	33
NV200	X11M	2014-4	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	16,123
NV200 Combi	X11M	2014-4	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	4,841
Pulsar	B12L	2014-3	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	61,501
Qashqai	P32S	2013-12	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	453,036

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Qashqai (LCV)	P32S	2013-12	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	302
Sentra	L12F	2014-8	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	16,287
Teana	L42L	2014-1	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	13,368
Tiida	B11C	2014-3	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	71
Tiida	B12L	2014-4	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	13,244
X-Trail	P32R	2013-11	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	78,200
X-Trail (LCV)	P32R	2013-11	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	108
<b>Renault</b>							
Espace	JFC	2014-12	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	19,836
Koleos	H45	2014-1	EOP	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	6,799
<b>4034</b>							
<b>Renault</b>							
C-CUV	HFE	2014-10	EOP	Conti	Info not available	Conti Snap-in TG1D 433MHz Renault	71,484
Espace (LCV)	JFC	2014-7	EOP	Conti	Info not available	Conti Snap-in TG1D 433MHz Renault	75
Laguna	LFD	2015-1	2021-09	Conti	Info not available	Conti Snap-in TG1D 433MHz Renault	2,566
Megane	BFB	2015-1	EOP	Conti	Info not available	Conti Snap-in TG1D 433MHz Renault	22,347
Megane		2015-4	2021-12	Conti	Info not available	Conti Snap-in TG1D 433MHz Renault	16,939
<b>4035</b>							
<b>Renault</b>							
Fluence	L38	2009-10	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	37,400
Laguna	X91	2007-10	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	47,848
Laguna (LCV)	X91	2007-6	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	32
Laguna Coupe	D91	2014-7	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	847
Laguna Coupe		2008-7	2014-06	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,611
Latitude	L43	2010-9	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	2,781
Megane	B32	2009-11	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	288
Megane	B32_X95	2011-5	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	18,956
Megane	X95	2008-11	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	170,897
Megane Van	BFB	2015-1	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	263
Megane Van	X95	2014-6	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	7,871
Scenic	J95	2015-1	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	91,147
Scenic		2009-1	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	146,726
Scenic (LCV)	J95	2009-2	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	96
Zoe	X10	2012-9	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	16,973
Zoe (LCV)	X10	2013-6	EOP	Conti	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	4
<b>4036</b>							
<b>Renault</b>							
Megane	X84	2002-11	2008-11	Conti	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	52,890
Megane Van	X84	2014-3	EOP	Conti	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	5
Scenic	J95	2003-6	2007-10	Conti	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	63,467
<b>4037</b>							
<b>Volkswagen</b>							
New Beetle	VW314	2006-1	2010-07	Conti	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	1,716
Passat	VW451	2005-3	2010-11	Conti	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	20,027

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>4038</b>							
<b>Mercedes-Benz</b>							
Sprinter (LCV)	NCV3	2006-6	2011-10	Conti	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	6,300
Viano (LCV) (Lo-Line)	W639	2003-7	2014-06	Conti	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	3,150
Viano (LCV) (Mid-Line)	W639	2003-7	2014-06	Conti	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	3,150
<b>Volkswagen</b>							
Crafter	VN830	2006-4	2017-09	Conti	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	16,081
Crafter Combi	VN830	2014-6	EOP	Conti	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	402
<b>4040</b>							
<b>Mercedes-Benz</b>							
CLS	C219	2005-1	2009-07	Conti	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	354
GL-Class	X164	2006-9	2009-07	Conti	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	59
R-Class	V251	2005-6	2009-07	Conti	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	443
S-Class	W221	2005-10	2009-06	Conti	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	2,955
SL	R230	2005-1	2009-07	Conti	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	1,182
<b>4043</b>							
<b>Alpina</b>							
Alpina 3	F30	2013-1	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	535
Alpina 3	F32	2013-4	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	471
Alpina 4	F32	2014-3	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	126
<b>BMW</b>							
1-Series	F20	2011-7	2019-12	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	180,720
1-Series (LCV)	F20	2014-6	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	49
2-Series	F22	2013-11	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	48,652
2-Series Active Tourer	F45	2014-7	2021-06	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	47,629
2-Series Gran Tourer	F46	2015-1	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	17,469
3-Series	F30	2011-11	2019-12	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	218,912
3-Series (LCV)	F30	2014-5	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	6
3-Series GT	F34	2013-3	2020-01	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	34,331
4-Series	F32	2013-10	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	82,255
4-Series Gran Coupe	F36	2014-7	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	30,305
i3	I01	2013-8	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	20,963
i8	I12	2014-1	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	3,209
X1	F48	2015-7	2021-12	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	9,048
X5	F15	2013-5	2020-03	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	84,785
X5 (LCV)	F15	2014-6	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	18
X6	F16	2014-8	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	17,438
<b>Mini</b>							
Clubman	F54	2015-7	2022-06	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	3,656
Clubman (LCV)	F54	2015-1	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	1
Clubvan	F54	2015-7	2022-05	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	255
Mini	F56	2013-12	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	159,514
Mini	R56	2014-6	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	21,993
Mini (LCV)	F56	2014-1	EOP	Conti	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	11
<b>4044</b>							
<b>Toyota</b>							
RAV4 (LCV)	120L	2005-11	2012-12	Pacific	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	204
<b>4045</b>							
<b>Aston Martin</b>							
Cygnnet	630L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
<b>Lexus</b>							
C-CUV	600A	2014-11	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	14,709
CT	080A	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	14,178
ES	980L	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3,958

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
GS	920L	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,484
GX	837L	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,296
IS	030L	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,022
IS	400A	2013-7	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	19,942
IS	720A	2015-2	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	684
LF-A	973L	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
LS	250L	2014-1	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,070
LX	220L	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,974
NX	600A	2014-3	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	17,567
RC	720A	2014-1	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,155
RX	640L	2014-6	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	8,769
RX	740A	2015-4	EOP	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	67
<b>Subaru</b>							
BRZ	E88	2014-1	EOP	Pacific	28103-CA101	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	1,452
<b>Toyota</b>							
Alphard	480L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	117
Alphard	580A	2015-5	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	109
Auris	130A	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	208,292
Auris	130L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Auris (LCV)	130A	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	32
Avalon	770N	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Avensis	312N	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Avensis	445L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	43,678
Avensis (LCV)	445L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Camry	050A	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,876
Camry	045L	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Corolla	079L, 140N, 340N	2013-8	EOP	Pacific	42607-42020	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	180
Corolla	140A	2014-1	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	408
Corolla	150A	2014-10	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,928
Corolla	366A	2013-9	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	110,268
Corolla	150L, 252L	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	368
Corolla	466A	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	78,032
Dyna	Dutro(2)	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	51
Dyna	U300-500	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7
Dyna	300-500, U600/C60	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12
Dyna	131N	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,496
FJ Cruiser	155L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
GT 86	E88	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,888
Hiace	550N	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	427
Highlander	440A	2014-10	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7,869
Highlander	397L	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Hilux	640A	2015-10	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,878
Hilux	669L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	20,829
IQ	630L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,402
Land Cruiser	215L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	14,012
Land Cruiser	611L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,999
Land Cruiser (LCV)	215L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	301
Land Cruiser Prado	611L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13,234
Land Cruiser V8	215L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	941
Previa	085X	2015-10	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13
Prius	590L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13,601
Prius	690A	2015-8	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	27
Prius (LCV)	590L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Prius (LCV)	690A	2015-9	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius Plus	030A	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	7,627

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
RAV4	410A	2013-1	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	22,970
RAV4 (LCV)	410A	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	37
Sienna	580L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	124
Tundra	180L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	24
Tundra	480A/180L	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	43
Urban Cruiser	260L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	479
Venza	470L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,225
Verso	151L,595L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	458
Verso	595L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	33,256
Verso (LCV)	595L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	97
Verso-S	770L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,011
Verso-S (LCV)	770L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Yaris	020L	2014-3	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Yaris	850L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	247,690
Yaris (LCV)	850L	2014-6	EOP	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	381
<b>4047</b>							
<b>Nissan</b>							
Juke	P12C	2015-10	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	29,348
Juke		2010-5	2015-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	136,498
Juke (LCV)	P12C	2010-5	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	52
Leaf	B12G	2010-10	EOP	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	20,328
<b>4048</b>							
<b>Peugeot</b>							
107	590N	2014-7	EOP	Pacific	(blank)	Pacific Clamp-in Fixed Angle ver 1 433MHz PSA/Toyota	940
<b>4052</b>							
<b>Hyundai</b>							
Equus	VI	2014-3	EOP	TRW	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	860
<b>Kia</b>							
Quoris	KH	2013-1	EOP	TRW	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	760
Rio (LCV)	QB	2014-3	EOP	TRW	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	13
<b>4053</b>							
<b>Hyundai</b>							
Elantra	HD	2014-3	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10
Elantra	MD	2014-3	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	11,859
<b>Kia</b>							
Rio	JB	2014-6	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	12
Rio	UB	2012-11	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	79,396
Rio (LCV)	UB	2000-1	EOP	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	44
<b>4054</b>							
<b>Alfa Romeo</b>							
159	939	2005-7	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	314
Brera	946	2005-11	2010-12	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	31
MITO	955	2008-6	2013-07	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	992
Spider	946	2006-6	2010-12	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	31
<b>Chrysler</b>							
Delta	844	2013-2	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	8
<b>Fiat</b>							
Bravo	198	2007-1	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	134
Punto	199	2005-9	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	70,871
<b>Lancia</b>							
Delta	844	2008-4	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	835
Delta (LCV)	844	2014-3	EOP	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	2
<b>4056</b>							
<b>Kia</b>							

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
Rio	QB	2000-1	EOP	Lear	52933-3J000	Lear Clamp-in Variable Angle ver 1 433MHz HKMC	144,083
<b>4057</b>							
<b>Hyundai</b>							
Santa Fe	CM	2005-12	EOP	Lear	52933-2B000	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	11
<b>4058</b>							
<b>Tesla</b>							
Model S	Model S	2013-5	2014-08	Baolong	FS1511	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	16,519
Model X	Model X	2015-8	EOP	Baolong	FS1511	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	25
<b>4059</b>							
<b>Hyundai</b>							
Genesis	BH	2014-6	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	12
Genesis	DH	2014-1	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	2,201
Genesis Coupe	BK	2014-3	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	446
i30	GD	2011-11	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	133,152
i30 (LCV)	GD	2011-10	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	11
ix20	JC	2013-5	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	50,001
Santa Fe	DM	2012-4	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	28,571
Santa Fe (LCV)	DM	2014-3	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	17
<b>Kia</b>							
Carens	RP	2012-12	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	5,262
Ceed	ED	2014-3	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	18
Ceed	JD	2012-3	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	136,376
Ceed (LCV)	JD	2014-3	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	10
New Carens	RP	2013-6	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	85
Picanto	TA	2014-4	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	91,389
Picanto (LCV)	TA	2014-6	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	32
Venga	YN	2014-4	EOP	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	28,188
<b>4060</b>							
<b>Hyundai</b>							
i20	PB	2014-7	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	4,653
iX35	TL	2015-10	EOP	Conti	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	6,743
iX35 (LCV)	TL	2015-10	EOP	Conti	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	1
<b>Kia</b>							
Cadenza	VG	2013-10	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	107
Magentis	TF	2014-3	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	2
Optima	TF	2013-8	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	5,575
Sorento	UM	2012-7	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	5,367
Sorento (LCV)	UM	2012-7	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	27
Sorento (LCV)	XM	2014-3	EOP	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	20
<b>4061</b>							
<b>Hyundai</b>							
Grandeur	HG	2014-3	EOP	TRW	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	337
i40	VF	2011-4	2014-03	TRW	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	3,229
i40 (LCV)	VF	2011-4	2014-03	TRW	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	4
<b>4062</b>							
<b>Hyundai</b>							
iX35	LM	2014-3	EOP	TRW	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	90,934
iX35 (LCV)	LM	2014-3	EOP	TRW	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	18
<b>Kia</b>							
Sportage	SL	2010-1	EOP	TRW	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	162,295
Sportage (LCV)	SL	2014-3	EOP	TRW	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	26
<b>4063</b>							
<b>Kia</b>							
Cerato	YD	2013-3	EOP	TRW	52933-A7100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	21,250

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>4064</b>							
<b>Honda</b>							
Jazz	2AP,2HQ	2014-6	EOP	TRW	Info not available	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	1,489
Jazz	2WF	2014-9	EOP	TRW	Info not available	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	29,463
Jazz	2AP	2014-3	EOP	TRW	Info not available	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	27,942
<b>4065</b>							
<b>Fiat</b>							
Sedici	YY2	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	581
<b>Opel</b>							
Agila	H0310	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,301
<b>Suzuki</b>							
Alto	YC5	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	16,410
Alto Van	YC5	2014-3	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1
Carry Van	YV7	2015-4	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	52
Celerio	YLA	2014-3	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	31,084
Grand Vitara	YT4	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	12,545
Grand Vitara (LCV)	YT4	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	36
Jimny	YR6,YR7	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,224
Jimny	YR7	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	8,848
Jimny (LCV)	YR7	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	100
Kizashi	YW1	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	327
Splash	YV1	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	12,175
Splash	YV1,YV4	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	10
Splash	YV4	2013-9	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,803
Splash	YV5	2015-5	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	13,551
Swift	YP6	2014-4	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	21,764
Swift	YP6,YP7	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	55,348
Swift (LCV)	YP6	2014-6	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	15
SX4	YY1	2013-8	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	84
SX4	YY1,YY3	2013-8	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	149
SX4	YY3	2014-3	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	5
SX4 S-Cross	YAA	2013-11	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	96,496
SX4 S-Cross (LCV)	YAA	2013-11	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	74
Vitara	YFA	2015-1	EOP	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	35,024
<b>4066</b>							
<b>Jaguar</b>							
RD-7	X760	2015-4	EOP	Conti	Unknown	Conti Clamp-in TG1C 433MHz JLR	16,975
XE	X760	2015-1	EOP	Conti	Unknown	Conti Clamp-in TG1C 433MHz JLR	21,566
XF	X260	2015-9	EOP	Conti	Unknown	Conti Clamp-in TG1C 433MHz JLR	1,860
<b>4067</b>							
<b>Skoda</b>							
Superb	SK481	2014-11	EOP	Huf	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	31,681
<b>Volkswagen</b>							
Passat	VW481	2014-7	EOP	Huf	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	68,525
Passat (LCV)	VW481	2014-7	EOP	Huf	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Touran	VW378	2015-1	EOP	Huf	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,256
Touran (LCV)	VW378	2015-1	EOP	Huf	Unknown	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	67

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>4068</b>							
<b>Jeep</b>							
Cherokee	KL	2014-3	EOP	TRW	68239720AB	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	15,341
Cherokee (LCV)	KL	2014-6	EOP	TRW	68239720AB	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	7
<b>Ram</b>							
1500	DS	2014-3	EOP	TRW	68239720AB	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	241
<b>4069</b>							
<b>Alpina</b>							
Alpina 5	F10	2014-3	2017-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	78
Alpina 6	F06	2014-3	2018-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	14
Alpina 6	F12	2015-1	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	4
Alpina 7	F01	2014-3	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	8
XD3	F25	2014-3	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	155
<b>BMW</b>							
5-Series	F10	2014-3	2016-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	109,786
5-Series GT	F07	2014-3	2017-03	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,397
6-Series	F12	2014-3	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	3,613
X1	E84	2014-3	2015-06	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	46,181
X1 (LCV)	E84	2014-3	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	3
X3	F25	2014-3	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	54,649
X3 (LCV)	F25	2014-6	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	14
X4	F26	2014-4	2020-03	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	32,024
Z4	E89	2014-3	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	4,862
<b>Mini</b>							
Countryman	R60	2014-7	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	54,019
Countryman (LCV)	R60	2014-7	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	7
Coupe	R58	2014-7	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	2,871
Paceman	R61	2014-7	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	7,046
Roadster	R59	2014-7	EOP	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	3,691
<b>4070</b>							
<b>Volvo</b>							
V40	Y555	2014-3	EOP	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	110,227
V40 (LCV)	Y555	2014-7	EOP	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	23
V40 XC	Y555	2014-3	EOP	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	20,179
V60	Y352	2014-7	2017-09	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	36,855
V60		2010-9	2014-06	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	9,677
V60 Cross Country	Y352	2015-1	EOP	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	2,196
V70	Y285	2014-7	EOP	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	6,662
V70		2006-3	2008-10	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	289
V70		2008-1	2014-06	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	6,297
XC60	Y413	2014-7	2016-10	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	58,278
XC60		2008-5	2014-06	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	15,391
XC70	Y381	2014-7	EOP	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	3,692
XC70		2007-2	2014-06	Conti	31341171	Conti Clamp-in TG1C 433MHz Volvo	4,125
<b>4071</b>							
<b>Infiniti</b>							
Q50	D53H	2013-4	EOP	Conti	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	5,019
Q50	L53H	2014-3	EOP	Conti	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	4,649
<b>Nissan</b>							
Altima	L42A	2014-3	EOP	Conti	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1
Murano	P42M	2014-10	EOP	Conti	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1,947
Murano (LCV)	P42M	2014-10	EOP	Conti	40700 3JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in Market in 2015
<b>4072</b>							
<b>Honda</b>							
Accord	2GB	2013-7	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	9,638
Accord	QE	2013-7	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	2,070
Accord CrossTour	2NX	2014-6	EOP	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	616
<b>4073</b>							
<b>Citroen</b>							
C4 Aircross	J4	2014-4	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	8,906
C4 Aircross (LCV)	J4	2014-4	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	15
C-ZERO	S4	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	991
C-ZERO (LCV)	S4	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	10
<b>Mitsubishi</b>							
ASX	ZC	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	50,399
ASX (LCV)	ZC	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11
i-MIEV	TQ	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,191
L200	4P00	2014-11	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	17,776
L200	4P00,CR	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	2,087
L200	CR	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11,549
Lancer	GS41	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	11,358
Lancer	JT41	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	327
Outlander	RE	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	58,191
Outlander	GS45X,RE	2014-3	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	918
Outlander (LCV)	RE	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	7
<b>Peugeot</b>							
4008	J3	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4,025
4008 (LCV)	J3	2014-6	EOP	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4
<b>4077</b>							
<b>Nissan</b>							
Micra	B02A	2010-3	EOP	Pacific	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	73,194
Micra (LCV)	B02A	2010-3	EOP	Pacific	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	4
<b>4078</b>							
<b>Hyundai</b>							
i40	VF	2014-4	EOP	TRW	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	35,028
<b>4079</b>							
<b>Mitsubishi</b>							
Attrage	EL-L	2014-3	EOP	Conti	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	440
Pajero	BK	2014-7	EOP	Conti	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	9,363
Pajero (LCV)	BK	2014-7	EOP	Conti	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	151
Pajero Sport	CR45	2014-6	EOP	Conti	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	7,108
Spacestar	EL	2014-7	EOP	Conti	4250C275	Conti Clamp-in TG1D 433MHz Conti Mitsubishi	28,341

## Euroguide -Service Kits Look Up

**Service Kits Look Up:** The application sensor list applied to a service kit is a list detailing which sensors can be serviced with that particular service kit. The number besides the code represents the quantity included in package (for example 5001 -10 means a package containing 10 Service kits)

- 1/ The first column "**Service Kits Part Nr./ Schrader Part Number (NEW)**" lists each service kit and identifies the sensors matching with the selected service kit (red references)
- 2/ The second column titled "**Service Kit Description**" shows the description of the selected service kit.
- 3/ The remaining column details the After Market "**Sensor Description**" of the sensor that can be serviced with the selected service kit.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk.

This list will be regularly updated. For further information: [tpmseuroshop.com](http://tpmseuroshop.com) or [aftermarket@schrader.co.uk](mailto:aftermarket@schrader.co.uk)

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
<b>5001-10</b>		
3042	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault grommet seal	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault
<b>5002-10</b>		
3040	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault conical seal coloured rings	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Renault
3043	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault conical seal coloured rings	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Conical Seal 433MHZ Renault
<b>5003-10</b>		
3004	Service Kit for SEL Clamp-in Gen2 type 433MHZ PSA PWM	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA
<b>5004-10</b>		
3026	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
3031	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
3037	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Nissan
3046	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Volvo
3058	Service Kit for SEL Gen2 conical seal	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
<b>5005</b>		
4036	Service Kit for Conti TG1B Renault	Conti Clamp-in TG1B Siemens VDO 433MHZ Renault
<b>5006</b>		
4031	Service Kit for Conti TG1B PSA Ford	Conti Clamp-in TG1B Siemens VDO 433MHz PSA
<b>5007</b>		
4037	Service Kit for Conti TG1B black nut VW	Conti Clamp-in TG1B Siemens VDO 433MHz VW
<b>5008</b>		
4040	Service Kit for Conti TG1B (MB) Daimler	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
<b>5014</b>		
4026	Service Kit for Conti TG1B HKMC	Conti Clamp-in TG1B 433MHz HKMC
<b>5015</b>		
4038	Service Kit for Conti TG1B (MB) Daimler	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler
<b>5016-10</b>		
3039	Service Kit for SEL Gen 3.1 Nissan	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan
<b>5017-10</b>		
3011	Service Kit for SEL Gen-Alpha Aluminium rims Daimler Chrysler WAL	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler
<b>5018</b>		
4035	Service Kit for Conti TG1C Renault	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
<b>5020</b>		
4019	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4065	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Suzuki
4021	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4070	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Volvo
4072	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti Honda
4066	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz JLR
<b>5021</b>		
4027	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
4060	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
<b>5022</b>		
4028	Service Kit for Conti TG1C Mazda	Conti Clamp-in TG1C 433MHz Mazda
<b>5024-10</b>		
3000	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz PSA
3001	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Ford
3027	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz GM
3049	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz GM
3056	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz GM
3068	Service kit Aluminium valve for SEL Snap-in Gen4 with valve	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
<b>5026-10</b>		
3000	Valve for for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz PSA
3001	Valve for for SEL Snap-in REV4 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz PSA HP

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
<b>5027-10</b>		
3053	Service Kit for SEL Gen-Alpha Chrysler WAL	Schrader Clamp-in Gen J 433MHz GM
<b>5028-10</b>		
3005	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Ford
3027	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz GM
3049	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz GM
3056	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz GM
3068	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
<b>5029-10</b>		
3008	Service Kit for SEL Gen-Alpha Chrysler FSK basic	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
<b>5030-10</b>		
3054	Service Kit for SEL Gen-J GM	Schrader Clamp-in Gen J 433MHz GM
3055	Service Kit for SEL Gen-J GM	Schrader Clamp-in Gen J 433MHz GM
<b>5031-10</b>		
2000	Valve for SEL EZ-sensor clamp-in 2000 part - includes mounting screw	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ-sensor@ sensor Europe
3070	Valve for SEL EZ-sensor clamp-in 2000 part - includes mounting screw	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
<b>5032-10</b>		
2000	Service Kit for SEL EZ-sensor clamp-in - without valve	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ-sensor@ sensor Europe
3070	Service Kit for SEL EZ-sensor clamp-in - without valve	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
2020	Service Kit for SEL EZ-sensor clamp-in - without valve	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ-sensor@ sensor Europe
<b>5033-10</b>		
1210	HSS replacement valve with screw	Schrader Snap-in Faraday 433Mhz programmable EZ-sensor@ 2.0 Europe
3041	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	HSS replacement valve with screw	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3012	HSS replacement valve with screw	Schrader Snap-in HS with 10deg angle 433MHz Daimler
3073	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Renault T4
3021	HSS replacement valve with screw	Schrader Snap-in Faraday 433MHz Ford
<b>5037-10</b>		
3033	Service Kit for SEL Gen Gamma GM	Schrader Clamp-in Gen Gamma 433MHz GM
<b>5038-10</b>		

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
2020	Valve for SEL EZ-sensor clamp-in 2020 part - includes mounting screw	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ-sensor® sensor Europe
<b>5056-10</b>		
3013	Service Kit for SEL Gen Gamma Mercedes	Schrader Clamp-in Gen Gamma 433MHz Daimler
2200	Service Kit for SEL Gen Gamma Mercedes	Schrader Delta 433Mhz programmable EZ-sensor® 2.0 Europe
<b>5057</b>		
4032	Service Kit for Conti TG1C Renault / Nissan	Conti Clamp-in TG1C 433MHz Renault
<b>5058</b>		
4043	Service Kit for Conti TG1C BMW / Mini	Conti Clamp-in TG1C 433MHz BMW
<b>5060-10</b>		
3009	Service Kit for SEL Gen Gamma Chrysler/Fiat	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat
<b>8001</b>		
3011	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler
3008	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
<b>8002-10</b>		
4035	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
4032	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Renault
4027	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz HKMC
4021	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Ford
4060	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz HKMC
<b>8003-10</b>		
4019	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Ford
4065	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Suzuki
4028	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz Mazda
4043	Aluminium valve stem for Conti TG1C with plastic cap	Conti Clamp-in TG1C 433MHz BMW
<b>8004-10</b>		
3000	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz PSA
3001	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Ford
3027	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz GM
3049	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz GM
3056	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz HKMC
3062	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz GM
3068	T10 Screw for Snap-in sensor valve REV4/REV5	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL