

## APDTY Nissan 350z or Infiniti G35 Window Motor or Switch Reset Procedure:

### Models With Window Motor Reset Button (Nissan 350z / Infiniti G35:

1. Get inside the vehicle and close the door.
2. With the door closed, lift UP and HOLD the window switch until the window is fully closed. Do not use the Window auto-closing function. Do not release the Switch before the Window is fully closed.
3. Press and hold the window regulator motor reset switch. While holding the Reset Switch: Press DOWN and HOLD the window switch until the window is fully open. Do not use the window auto-opening function. Do not release the switch before the window is fully open.
4. Release the Reset Switch. Then lift UP and HOLD the window switch button until the window is fully closed. Do not use the window auto closing function. Do not release the switch before the window is fully closed.
5. Open the door to release to door switch. The window glass should partially move down.

### Models Without Reset Button On The Window Motor:

After window switch or motor installation is complete, perform these steps to rest the limit switch and program the auto-function.

- 1 Roll the window all the way down by depressing and holding the window down button, continue to hold the window down button for a full 5 seconds after the window has fully rolled down. Release the button.
- 2 Roll the window all the way up by depressing and holding the window up button, continue to hold the window up button for a full 5 seconds after the window has fully rolled down. Release the button.

\*\*Note: This assumes a proper diagnosis was performed originally to verify you needed a window motor or switch in the first place.

\*\*Note: Disconnecting a window switch or motor can cause the limit switch to need to be rest again.