

Headset Connection List for Panasonic Products

		TGL46x / TGM43x TGE46x / TGE47x (TG654 / TG684)	TGF37x / TGF38x (TG585 / TG175)	TGE26x / TGE27x TGH26x (TG454 / TG465 / TG472 / TG473)	TG958x / TG954x	TG78xx (TG365 / TG385 / TG395)
Bland	Model	All	All	All	All	All
BlackBerry	HS-500	OK	OK	OK	OK	OK
BlueAnt	V1	OK *1	OK *1	OK *1	OK *1	OK *1
BlueAnt	T1	x *7	x *7	x *7	x *7	x *7
Bose	Bluetooth	OK	OK	OK	OK	OK
Jabra	BT2010	OK *4	OK *4	OK *4	OK *4	OK *4
Jabra	BT2070	OK	OK	OK	OK	OK
Jabra	BT2080	OK	OK	OK	OK	OK
Jabra	STONE2	OK *5	OK *5	OK *5	OK *5	OK *5
Jabra	Wave	OK	OK	OK	OK	OK
Jabra	Mini	OK	OK	OK	-	-
Jawbone	PRIME	OK *2 *3	OK *2 *3	OK *2 *3	OK *2 *3	OK *2 *3
Jawbone	ICON	OK	OK	OK	OK	OK
Motorola	H560	OK	OK	OK	OK	OK
Motorola	H720	OK *6	OK *6	OK *6	OK *6	OK *6
Motorola	H385	OK	OK	OK	OK	OK
Nexus	BluemoosePRO	OK	OK	OK	OK	OK
Nokia	BH-104	OK	OK	OK	OK	OK
Nokia	BH-213	OK	OK	OK	OK	OK
Philips	SHB1400	OK	OK	OK	OK	OK
Phonak	ComPilot Air II	-	OK	-	-	-
Plantronics	Discovery 925	OK	OK	OK	OK	OK
Plantronics	Discovery975	OK *2	OK *2	OK *2	OK *2	OK *2
Plantronics	Voyager 520	OK	OK	OK	OK	OK
Plantronics	Voyager Pro	OK	OK	OK	OK	OK
Plantronics	Voyager PRO+	OK	OK	OK	OK	OK
Plantronics	Explorer 240	OK	OK	OK	OK	OK
Samsung	WEP-450	OK	OK	OK	OK	OK
Samsung	WEP-470	OK	OK	OK	OK	OK
Samsung	HM1100	OK	OK	OK	OK	OK
SonyEricsson	VH-110	OK	OK	OK	OK	OK
Sound ID	510	x *7	x *7	x *7	x *7	x *7

-	not evaluate
x	evaluated but not be compatible

- *1 Connection is not stable when a cellular phone is connected to base unit too.
- *2 No beep sounds from headset during incoming calls
- *3 Cannot end talk by headset talk key during headset talk.
(To end talk, need to press baseunit SP-Phone key.)
- *4 To seize the line, double click headset talk key.
If user click headset key single, then user can never seize the line by headset talk key.
This phenomenon will be improved by disconnecting and connecting headset again.
- *5 Headset beeps only 1 time(does not sound repeatedly) during incoming calls.
- *6 Beep sound interval is not stable during incoming calls.
- *7 This headset doesn't support bluetooth HSP profile.

Headset Connection List for Panasonic Products

Bland	Model	TGE26x/TGE27x /TGH26x (TG454/TG465/ TG472/TG473)	TG954x	TG78xx (TG365/TG385 /TG395)	TG77xx (TG254/TG265 /TG294)	TG76xx (TG155)	TG658x		TG938x	
		All	All	All	All	All	Suffix A ~ D	Suffix E ~	Suffix A ~ C	Suffix D ~
BlackBerry	HS-500	OK	OK	OK	OK	OK	-	OK	-	OK
BlueAnt	V1	OK *1	OK *1	OK *1	OK *1	OK *1	OK *1	OK *1	OK	OK
BlueAnt	T1	x *7	x *7	x *7	x *7	x *7	-	-	-	-
Bose	Bluetooth	OK	OK	OK	OK	OK	-	OK	-	OK
Jabra	BT250V	-	-	-	OK	OK	OK	OK	OK	OK
Jabra	BT320s	-	-	-	OK *3	OK *3	OK *3	OK *3	OK *3	OK *3
Jabra	BT2020	-	-	-	OK	OK	OK	OK	OK	OK
Jabra	BT2010	OK *4	OK *4	OK *4	OK *4	OK *4	OK *4	OK *4	OK *4	OK *4
Jabra	BT2070	OK	OK	OK	OK	OK	OK	OK	OK	OK
Jabra	BT2080	OK	OK	OK	OK	OK	OK	OK	OK	OK
Jabra	STONE2	OK *5	OK *5	OK *5	OK *5	OK *5	-	OK *5	-	OK
Jabra	Wave	OK	OK	OK	OK	OK	-	OK	-	OK
Jawbone	PRIME	OK *2 *3	OK *2 *3	OK *2 *3	OK *2 *3	OK *2 *3	x	OK *2 *3	x	OK *2 *3
Jawbone	ICON	OK	OK	OK	OK	OK	OK	OK	OK	OK
Motorola	H710	-	-	-	OK	OK	OK	OK	OK	OK
Motorola	H680	-	-	-	OK	OK	OK	OK	OK	OK
Motorola	H560	OK	OK	OK	OK	OK	OK	OK	OK	OK
Motorola	H720	OK *6	OK *6	OK *6	OK *6	OK *6	-	OK *6	-	OK *5
Motorola	H385	OK	OK	OK	OK	OK	-	OK	-	OK
Nexxus	TalknanoPROMini	-	-	OK	OK	OK	OK	OK	OK	OK
Nexxus	BluemusicPRO	OK	OK	OK	OK	OK	OK	OK	OK	OK
Nokia	BH-104	OK	OK	OK	OK	OK	OK	OK	OK	OK
Nokia	BH-213	OK	OK	OK	OK	OK	OK	OK	OK	OK
Philips	SHB1400	OK	OK	OK	OK	OK	-	-	-	-
Plantronics	665	-	-	-	OK	OK	OK	OK	OK	OK
Plantronics	Discovery 925	OK	OK	OK	OK	OK	OK	OK	OK	OK
Plantronics	Discovery975	OK *2	OK *2	OK *2	OK *2	OK *2	OK *2	OK *2	OK *2	OK *2
Plantronics	Voyager 520	OK	OK	OK	OK	OK	OK	OK	OK	OK
Plantronics	Voyager Pro	OK	OK	OK	OK	OK	OK	OK	OK	OK
Plantronics	Voyager PRO+	OK	OK	OK	OK	OK	-	OK	-	OK
Plantronics	Explorer 240	OK	OK	OK	OK	OK	-	OK	-	OK
Samsung	WEP350	-	-	-	OK	OK	OK	OK	OK	OK
Samsung	WEP-450	OK	OK	OK	OK	OK	OK	OK	OK	OK
Samsung	WEP-470	OK	OK	OK	OK	OK	OK	OK	OK	OK
Samsung	HM1100	OK	OK	OK	OK	OK	-	OK	-	OK
SonyEricsson	HBH-610	-	-	-	-	-	OK	OK	OK	OK
SonyEricsson	HBH-PV703	-	-	-	OK	OK	OK	OK	OK	OK
SonyEricsson	VH310	-	-	-	OK	OK	OK	OK	OK	OK
SonyEricsson	VH-110	OK	OK	OK	OK	OK	-	OK	-	OK
Sound ID	510	x *7	x *7	x *7	x *7	x *7	-	-	-	-

- not evaluate
x evaluated but not be compatible

- *1 Connection is not stable when a cellular phone connects to base unit too.
- *2 No beep sounds from headset during incoming calls
- *3 Cannot end talk by headset talk key during headset talk.
(To end talk, need to press baseunit SP-Phone key.)
- *4 To seize the line, double click headset talk key.
However if user click headset key single,
then user can never seize the line by headset talk key.
This phenomenon will improve after disconnecting and connecting headset again.
- *5 Headset beeps only 1 time(does not sound repeatedly) during incoming calls.
- *6 Beep sound interval is not stable during incoming calls.
- *7 This headset doesn't support bluetooth HSP profile.