


Charge

Your new headset has enough power to pair and make a few calls before charging is needed, though you may charge at any time.

- 1 Align snap-fit magnetic areas of headset and USB cable.



- 2 Attach cable to USB wall charger or laptop for 90 minutes. LEDs turn off once fully charged.




Table 1: Headset LED behavior while charging

Off	Charging complete
● ● ●	Battery high
● ●	Battery medium
● ●	Battery low
● ● ●	Battery critical