


H Series



Ref. #	Model #	Generic Part #	Eng. Part #	Description
1	H-100-HD		37-112-008	Pivot Pin 13/16x12 1/2
2	H-100-HD		37-145-001	Release Cable
3	H-100-HD		37-025-002	Release Handle
4	H-100-HD		64141	Spring Pin 3/16x2
5	H-100-HD		33444	Machine Bushing 18 ga x 1"
6	H-100-HD		37-145-002	Chain 5/16
6	H-100-HD		08-145-027	Yellow 36" Restraint Strap
7	H-100-HD		74627	Quick Link
8	H-100-HD		37-146-001	Spring
	H-100-HD	MC-0826-01	37-146-005	Round Torsion Spring (new in 2006)
9	H-100-HD			Release Lever Assembly , Only Available As Assembly
10	H-100-HD		37-145-003	Cable Crimp
11	H-100-HD		29-048-060	Bumper
12	H-100-HD		11062	Bolt 5/16 - 18 x 2 1/4
13	H-100-HD		36104	Nut 5/16 - 18
1	H-100-LD		37-112-008	Pivot Pin 13/16x12 1/2
2	H-100-LD		37-145-001	Release Cable
3	H-100-LD		37-025-002	Release Handle
4	H-100-LD		64141	Spring Pin 3/16x2
5	H-100-LD		33444	Machine Bushing 18 ga x 1"
6	H-100-LD		37-145-002	Chain 5/16
6	H-100-LD		08-145-027	Yellow 36" Restraint Strap
7	H-100-LD		74627	Quick Link
8	H-100-LD		37-146-001	Spring
	H-100-LD	MC-0826-01	37-146-005	Round Torsion Spring (new in 2006)
9	H-100-LD	H-100-LD-LAA		Release Lever Assembly , Only Available As Assembly
10	H-100-LD		37-145-003	Cable Crimp
11	H-100-LD		29-048-060	Bumper
12	H-100-LD		11062	Bolt 5/16 - 18 x 2 1/4
13	H-100-LD		36104	Nut 5/16 - 18
1	H-100-MD		37-112-008	Pivot Pin 13/16x12 1/2
2	H-100-MD		37-145-001	Release Cable
3	H-100-MD		37-025-002	Release Handle
4	H-100-MD		64141	Spring Pin 3/16x2
5	H-100-MD		33444	Machine Bushing 18 ga x 1"
6	H-100-MD		37-145-002	Chain 5/16
6	H-100-MD		08-145-027	Yellow 36" Restraint Strap
7	H-100-MD		74627	Quick Link
8	H-100-MD		37-146-001	Spring
	H-100-MD	MC-0826-01	37-146-005	Round Torsion Spring (new in 2006)
9	H-100-MD			Release Lever Assembly , Only Available As Assembly
10	H-100-MD		37-145-003	Cable Crimp
11	H-100-MD		29-048-060	Bumper
12	H-100-MD		11062	Bolt 5/16 - 18 x 2 1/4
13	H-100-MD		36104	Nut 5/16 - 18
1	H-150-LD		37-112-008	Pivot Pin 13/16x12 1/2
2	H-150-LD		37-145-001	Release Cable
3	H-150-LD		37-025-002	Release Handle
4	H-150-LD		64141	Spring Pin 3/16x2
5	H-150-LD		33444	Machine Bushing 18 ga x 1"
6	H-150-LD		37-145-002	Chain 5/16
6	H-150-LD		08-145-027	Yellow 36" Restraint Strap

7	H-150-LD		74627	Quick Link
8	H-150-LD		37-146-001	Spring
	H-150-LD	MC-0826-01	37-146-005	Round Torsion Spring (new in 2006)
9	H-150-LD	H-150-LAA		Release Lever Assembly , Only Available As Assembly
10	H-150-LD		37-145-003	Cable Crimp
11	H-150-LD		29-048-060	Bumper
12	H-150-LD		11062	Bolt 5/16 - 18 x 2 1/4
13	H-150-LD		36104	Nut 5/16 - 18
1	H-150-MD		37-112-008	Pivot Pin 13/16x12 1/2
2	H-150-MD		37-145-001	Release Cable
3	H-150-MD		37-025-002	Release Handle
4	H-150-MD		64141	Spring Pin 3/16x2
5	H-150-MD		33444	Machine Bushing 18 ga x 1"
6	H-150-MD		37-145-002	Chain 5/16
6	H-150-MD		08-145-027	Yellow 36" Restraint Strap
7	H-150-MD		74627	Quick Link
8	H-150-MD		37-146-001	Spring (EXTENTION)
	H-150-MD	MC-0826-01	37-146-005	Round Torsion Spring (new in 2006)
9	H-150-MD		H-150-MD-LAA	Release Lever Assembly , Only Available As Assembly
10	H-150-MD		37-145-003	Cable Crimp
11	H-150-MD		29-048-060	Bumper
12	H-150-MD		11062	Bolt 5/16 - 18 x 2 1/4
13	H-150-MD		36104	Nut 5/16 - 18
1	H-25-HD		37-112-008	Pivot Pin 13/16x12 1/2
2	H-25-HD		37-145-001	Release Cable
3	H-25-HD		37-025-002	Release Handle
4	H-25-HD		64141	Spring Pin 3/16x2
5	H-25-HD		33444	Machine Bushing 18 ga x 1"
6	H-25-HD		37-145-002	Chain 5/16
6	H-25-HD		08-145-027	Yellow 36" Restraint Strap
7	H-25-HD		74627	Quick Link
8	H-25-HD		37-146-001	Spring
	H-25-HD	MC-0826-01	37-146-005	Round Torsion Spring (new in 2006)
9	H-25-HD			Release Lever Assembly , Only Available As Assembly
10	H-25-HD		37-145-003	Cable Crimp
11	H-25-HD		29-048-060	Bumper
12	H-25-HD		11062	Bolt 5/16 - 18 x 2 1/4
13	H-25-HD		36104	Nut 5/16 - 18
1	H-50		37-112-008	Pivot Pin 13/16x12 1/2
2	H-50		37-145-001	Release Cable
3	H-50		37-025-002	Release Handle
4	H-50		64141	Spring Pin 3/16x2
5	H-50		33444	Machine Bushing 18 ga x 1"
6	H-50		37-145-002	Chain 5/16
6	H-50		08-145-027	Yellow 36" Restraint Strap
7	H-50		74627	Quick Link
8	H-50		37-146-001	Spring
	H-50	MC-0826-01	37-146-005	Round Torsion Spring (new in 2006)
9	H-50			Release Lever Assembly , Only Available As Assembly
10	H-50		37-145-003	Cable Crimp
11	H-50		29-048-060	Bumper
12	H-50		11062	Bolt 5/16 - 18 x 2 1/4
13	H-50		36104	Nut 5/16 - 18