


Sampling B010U3XO3Q inventory to test function

1. Purpose :

Customer feedback Lightning cable B010U3XO3Q did not work, so resampling the factory inventory to test its function.

2. Test Machine:

voltage-drop test machine, Ipad, computer



3. Test Procedure :

Step 1. The quantity of inventory is 28482pcs, and sampling 315pcs products to test function according to the sampling plan of Z1.4



Step 2. Using the voltage-drop test machine to confirm the cable electrical specification



Step 3. Using the Ipad and computer to confirm cable actual using function



Step 4. The function test result of 315pcs sample

Number	1	2	3	4	5	6	7	8	9	10
voltage-drop tes result										
	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
Number	11	12	13	14	15	16	17	18	19	20~315
voltage-drop tes result										
	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
Number	1	2	3	4	5	6	7	8	9	10
simulation test result										
	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
Number	11	12	13	14	15	16	17	18	19	20~315
simulation test result										
	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK

4. Conclusion :

The function of inventory products are all OK.